

14-Mar-08

## Well Inspection History

API Number: **30-015-10254-00-00**

Well Name & No.: **RESLER YATES STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER D**

District: **ARTESIA**

County Name: **EDDY**

Field: **RESLER YATES STATE**

Legal: **S: 21 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/25/2007	Routine/Periodic	Normal Routine Activity	IMLB07206399		211		
	Well is pumping. Heavy contamination at well head area.						
8/30/2005	Routine/Periodic	Normal Routine Activity	IMLB05242404		211		
	Well is pumping. Heavy contamination at well head area with oil pooled at wellhead.						
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423332		209		
	Well appears able to produce. Last reported production Jan 2004 (Zero).						
1/6/2004	Routine/Periodic	Normal Routine Activity	iPCH0400642		210		
	Location needs attention. Equipment OK.						
10/19/1999	Routine/Periodic	Status Check	iELG0002968		207		
	A-OK. All Equipment and Location in Good Shape.						

**Total Inspections Performed: 5**

**Jackie Brewer D/B/A  
Sandlott Energy  
Case 14074  
OCD Exhibit No. 7**