

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

JUL 13 2007
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
OCD-ARTESIA

30-015-05688
05687

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Americo Energy Resources, LLC	Contact Oscar Nosrati
Address 7575 San Felipe, #200, Houston, TX 77063	Telephone No. 713-984-9700
Facility Name East Shugart Unit #16 Injection Well	Facility Type Injection Well
Surface Owner BLM #15	Mineral Owner BLM
Lease No. NM-10192	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	34	18 S	31 E	2,310	North	2,310	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water and oil	Volume of Release 150 bbls.	Volume Recovered 130 bbls.
Source of Release	Date and Hour of Occurrence 6/24/07 a.m.	Date and Hour of Discovery 6/24/07 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gerry Guye	
By Whom? Don Gray	Date and Hour 6/25/07 1:20 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Injection well supply line ruptured. Replaced line.		
Describe Area Affected and Cleanup Action Taken.* 150 total bbls of fluid (+/- 95% salt water) released predominantly on road and pad with approximately a 30' x 100' additional area affected. Contracted Quannah Services' vacuum trucks to recover fluid. Successfully recovered approximately 90% of released fluid.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert M. (Don) Gray	Approved by District Supervisor: 	
Title: Land Manager	Approval Date: JUL 13 2007	Expiration Date:
E-mail Address: don.gray@amicoenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 7/6/07	Phone: 713-984-9700	

* Attach Additional Sheets If Necessary

Americo Energy Resources, LLC

Case 14079
OCD Exhibit No. 6