

28-Aug-08

## Well Inspection History

API Number: **30-015-10254-00-00**

Well Name & No.: **RESLER YATES STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER DB** District: **ARTESIA** County Name: **EDDY**

Field: **RESLER YATES STATE**

Legal: **S: 21 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
8/4/2008	Routine/Periodic	Normal Routine Activity	iGEG0821741		209		
Well is not pumping. Took photos.							
7/15/2008	Routine/Periodic	Normal Routine Activity	iMLB08197449		211		
Met on site with Jackie Brewer (Sandlott) and Al Nassar (new partner). Intent was to obtain samples at well head area. Excavated to just over 1' depth and backhoe broke down. Will get different backhoe and meet in the morning.							
7/25/2007	Routine/Periodic	Normal Routine Activity	iMLB07206399		211		
Well is pumping. Heavy contamination at well head area.							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242404		211		
Well is pumping. Heavy contamination at well head area with oil pooled at wellhead.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423332		209		
Well appears able to produce. Last reported production Jan 2004 (Zero).							
1/6/2004	Routine/Periodic	Normal Routine Activity	iPCH0400642		210		
Location needs attention. Equipment OK.							
10/19/1999	Routine/Periodic	Status Check	iELG0002968		207		
A-OK. All Equipment and Location in Good Shape.							

**Total Inspections Performed: 7**

**Jackie Brewer D/B/A  
Sandlott Energy  
De Novo Case 14074  
OCD Exhibit No. 8**

Resler Yates State #317