

28-Aug-08

## Well Inspection History

API Number: **30-015-10285-00-00**

Well Name & No.: **RESLER YATES STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER DB**

District: **ARTESIA**

County Name: **EDDY**

Field: **RESLER YATES STATE**

Legal: **S: 20 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
8/4/2008	Routine/Periodic	Normal Routine Activity	iGEG0821744		209		
Well is not pumping. Took photos.							
7/25/2007	Routine/Periodic	Normal Routine Activity	iMLB07206434		211		
Well is pumping. Heavy contamination at well head area and out onto location.							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242392		211		
Well appears capable of producing. No indication of recent activity at well site. Heavy contamination at wellhead area and out onto location.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423333		209		
Electricity off. Well appears able to produce. Last reported production Jan 2004. Area contaminated.							
10/19/1999	Routine/Periodic	Status Check	iELG0002995		207		
A-OK. All Equipment and Location in Good Shape.							

**Total Inspections Performed: 5**

**Jackie Brewer D/B/A  
Sandlott Energy  
De Novo Case 14074  
OCD Exhibit No. 9**