

28-Aug-08

Well Inspection History

API Number: **30-015-20094-00-00**

Well Name & No.: **RESLER YATES STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER DB** District: **ARTESIA** County Name: **EDDY**

Field: **RESLER YATES STATE**

Legal: **S: 32 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/24/2007	Routine/Periodic	Normal Routine Activity	iMLB07205440		211		
		Contamination and oil standing around pumping unit. Electric meter has been pulled at the well site but an electric line has been laid to a power meter near the Resler Yates 381 well. No indication of recent activity at this well site other than the standing oil.					
7/5/2006	File and Compliance Review	Normal Routine Activity	iPCH0618641		210		
		No belts on pumping unit motor, no electrical hook up. Contamination around wellhead					
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242536		211		
		No Motor on Pumping Unit. No indication of recent activity at well site.					
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423339		209		
		No Motor on Pumping Unit.					
10/19/1999	Routine/Periodic	Status Check	iELG0003125		207		
		A-OK. All Equipment and Location in Good Shape.					

Total Inspections Performed: 5

**Jackie Brewer D/B/A
Sandlott Energy
De Novo Case 14074
OCD Exhibit No. 11**

Resler Yates State #370