

28-Aug-08

Well Inspection History

API Number: 30-015-02672-00-00

Well Name & No.: THOMAS STATE

Operator: SANDLOTT ENERGY (JACKIE BREWER DB District: ARTESIA County Name: EDDY

Field: THOMAS STATE

Legal: S: 9 T: 18S R: 28E

Well Type: OIL (PRODUCING)

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/25/2007	Routine/Periodic	Normal Routine Activity	IMLB07206381		211		
No pumping unit on well. Heavy contamination at well head area. Numerous areas of contamination at tank battery situated just West of well.							
7/10/2006	Routine/Periodic	Normal Routine Activity	iVAB06191383		208		
7/3/2006	File and Compliance Review	Normal Routine Activity	iPCH0618440		210		
No electric meter or power to pumping unit. Large area of release and contamination at well head, flow line, around tanks, knock outs, and pumps. Tanks leaking.							
10/20/2005	Compliance Verification	Normal Routine Activity	ICLB05293393		212		
Took samples along north side of tanks. Sample 1: 32.76657N 104.17403W 6 inches Sample 2: 32.76660N 104.17835W 6 inches Sample 3: 32.76671N 104.17400W 6 inches							
Tanks: 1: 32.76668N 104.17410W 2: 32.76665N 104.17409W 3: 32.76661N 104.17411W 4: 32.76664N 104.17403W							
Tank 4 is horizontal oil and gas separator.							
Gun barrel: 32.76655N 104.17408W							
Gun barrel has been moved and is lying on it's side approx 50 feet south of original location.							
8/29/2005	Routine/Periodic	Normal Routine Activity	IMLB05241534		211		
No indication of recent activity at well site. Electric meter has been pulled at pole. Tank battery located West of well site has tank leaking what appears to be produced water. Leak appears to be in bottom of tank producing a slow trickle out from under tank. Various other areas of contamination at battery.							
8/19/2004	Routine/Periodic	Normal Routine Activity	IGEG0423249		209		
Electricity off.							
11/12/2002	Routine/Periodic	Normal Routine Activity	IMLB02318566		211	Y	
Tank battery for this well has numerous leaks. Produce water is standing in several areas and has run out into pasture approx. 50-75 yards. Violation Rule 13 and Rule 116.							
10/8/2002	Routine/Periodic	Normal Routine Activity	IMLB02281435		211		
Some contamination at well head. Check production. PJ BT							
10/18/1999	Routine/Periodic	Status Check	iELG0002503		207		
A-OK. All Equipment and Location in Good Shape. B/T							

Total Inspections Performed: 9

Jackie Brewer D/B/A
Sandlott Energy
De Novo Case 14074
OCD Exhibit No. 13

Thomas State #001