

Exhibit 6

13-Feb-09

Well Inspection History

API **30-025-23891-00-00**

Well Name && No.: **CROSBY DEEP**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **CROSBY DEEP**

Legal: **S: 28 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903738		122		
	Well is not plugged. No record of pressure test. Took picture. MW						
5/3/2005	File and Compliance Review	Status Check	iSAD0512353		118		
	NOI TO P&A APRVD BY FEDS 3/05;						
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000671		114		
	SI/O N/UNIT N/FL						

Total Inspections

3

Case No. 14106, De Novo
Re Xeric Oil & Gas
OCD EXHIBIT No. 6

XERIC OIL & GAS CORPORATION

CROSBY DEEP WELL NO. 1
SE/SW, SEC. 28 - T25S-R37E
LEA COUNTY, NEW MEXICO

71319









13-Feb-09

Well Inspection History

API **30-025-24287-00-00**

Well Name && No.: **CROSBY DEEP**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **CROSBY DEEP**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903744		122		
Well idle. No flowlines connected to wellhead. Oil seeping from wellhead. Rods stacked out in tubing. Sub cable also sticking out of wellhead. Location has been scraped and leveled. Piping and other junk metal north of well. Large excavation on east side of location. Oil stained soil on NW corner of location. Took pictures. MW							
4/10/2006	Routine/Periodic	Normal Routine Activity	iLWH0610060		102	Y	109 114
Idle Well (Rule 201), OIL LEAKING OUT WELLHEAD. NEEDS LEAK STOPPED AND WELL T/A, P/A OR PUT BACK IN USE. FIRST NOTICE							
10/25/2005	Compliance Verification	Enforcement Action Follow-	iLWH0529848		102		
OIL INSIDE DYKE COVERED W/ SAND. FENCE PUT UP. WELL STILL IDLE.							
7/21/2005	Routine/Periodic	Normal Routine Activity	iLWH0520250		102	Y	109 114
OIL PUDDLE INSIDE DYKE, 5' X 10', NOT LINED OR FENCED, HEAVY STAIN EVERYWHERE. NEEDS CLEANED UP PER NMOC D GUIDELINES. CALL LARRY JOHNSON @ 505-393-6161 EXT. 111..NO P/U, CHECK PROD.. TOOK PICTURES.. IDLE WELL ,NEEDS T/A, P/A OR PUT BAQCK IN USE..FIRST NOTICE							
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000703		114		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections

5

XERIC OIL & GAS CORPORATION

CROSBY DEEP WELL NO. 2
SW/NE/4, SEC. 33-T25S-R37E
LEA CO., NM N.M. LOC 54667











13-Feb-09

Well Inspection History

API Number: **30-025-11870-00-00**

Well Name & No.: **CROSBY DEEP**

Operator: **XERIC OIL & GAS CORP, VICTORIA HIRSC**

District: **HOBBS**

County Name: **LEA**

Field: **CROSBY DEEP**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903741		122		
Well idle. No flowlines connected to wellhead. No record of recent pressure test. Location has been scraped and leveled. Took pictures. MW							
8/27/2007	Compliance Verification	Enforcement Action Follow-u	iLWH0723955		102		
WELL SIGN OK ! WELL IS SI-D							
7/1/2005	Routine/Periodic	Normal Routine Activity	iLWH0518260		102	Y	100
WELL SIGN HAS 'GREGORY EL PASO FED. #3,,,1980' FSL--1980' FWL,,,SEC. 23"..NEEDS WELL CORRECTED. WILL CHECK T/A STATUS. FIRST NOTICE							

Total Inspections Performed: 3

XOG OPERATING, LLC

(888) 683-3171

CROSBY DEEP #3

1980' FSL & 1980' FEL

UNIT J, SEC.33-T25S-R37E

LEA COUNTY, NM

API #30-025-11870



XOG OPERATING, LLC

(888) 663-3171

GROSBY DEEP #3

1980' FSL & 1980' FEL

UNIT J, SEC.33-123S-R37E

LEA COUNTY, NM

API #30-925-11670

13-Feb-09

Well Inspection History

API **30-025-25985-00-00**

Well Name && No.: **CROSBY DEEP**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **CROSBY DEEP**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903739		122		
Well idle. Sub pump cable sticking out of wellhead. All valves closed running toward separator. Surplus equipment and other debris south of location. Pumping unit base on west side. Sub pump controller on NW corner. Location has been leveled and scraped off. MW							
3/17/2005	Routine/Periodic	Normal Routine Activity	iLWH0507659		102		
OK. All Equipment and Location in Good Shape.							
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000666		114		
A-OK. All Equipment and Location in Good Shape.							


Total Inspections

3

XERIC OIL & GAS CORPORATION

CROSBY DEEP NO. 4
NE/4, NW/4, SEC. 33
T25S, R37E, SW-976
LEA COUNTY, NEW MEXICO

XERIC OIL & GAS CORPORATION
CROSBY DEEP NO. 4
NE 1/4, NW 1/4, SEC. 33
T25S, R37E, SW-976
LEA COUNTY, NEW MEXICO





13-Feb-09

Well Inspection History

API **30-025-11884-00-00**

Well Name && No.: **GREGORY A**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **GREGORY A**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **SALT WATER DISPOSAL WELL**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903741		122		
Well idle. No flowlines connected to wellhead. Netting on tank west of well has fallen into tank. Location scraped and leveled. Took pictures. MW							
8/27/2007	Routine/Periodic	Normal Routine Activity	iLWH0723952		102		
OK. All Equipment and Location in Good Shape. NEEDS BHT, CALLED SAD							
7/21/2005	File and Compliance Review	Status Check	iSAD0520252		118		
7/21/05 CALLED XERIC IN MIDLAND GLENDA WILL HAVE ANGIE CRAWFORD SEND IN PAPERWORK FOR WELL. IT HAS BEEN CONV. PER SWD-887. (SAD)							
7/21/2005	Routine/Periodic	Normal Routine Activity	iLWH0520248		102		
WELL IS ACTIVE SWD.							
4/30/2003	Pressure Test	Request/Complaint	iLWH0312033		102		
A-OK. All Equipment and Location in Good Shape. CONVERTING TO INJ..							
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000700		114		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections


6

XERIC OIL & GAS CORP.

GREGORY A NO. 5
1980 FSL & 660 FEL (I)
SEC. 33, T-25-S, R-37-E
LEA CO., NEW MEXICO
LEASE NO. LC-054667
G. L. = 3004

XERIC OIL & GAS CORP
GREGORY A NO 5
1980 FSL G 660 FEL (I)
SEC 33, T-25-S, R-37-E
LEA CO, NEW MEXICO
LEASE NO. LC-054667
G. L. # 3004





13-Feb-09

Well Inspection History

API **30-025-11867-00-00**

Well Name && No.: **GREGORY A**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **GREGORY A**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903740		122		
	Well appears idle. Pumping unit on well and rods in tubing. 1" valve on off side of pumping tee open. Took pictures. MW						
8/27/2007	Routine/Periodic	Normal Routine Activity	iLWH0723956		102		
	OK. All Equipment and Location in Good Shape.						
7/1/2005	Routine/Periodic	Normal Routine Activity	iLWH0518259		102		
	OK. All Equipment and Location in Good Shape.						
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000694		114		
	A-OK. All Equipment and Location in Good Shape.						

Total Inspections

4

RIC OIL & GAS CORP.

GREGORY A NO. 7
660 FSL & 1880 FWL (N)
SEC. 33, T-25-S, R-37-E
LEA CO., NEW MEXICO
LEASE NO. LC-504667
G. L. = 2989

ON

AY
ICALLY
E

KING





13-Feb-09

Well Inspection History

API 30-025-29539-00-00

Well Name && No.: GREGORY A

Number:

Operator: XERIC OIL & GAS CORP, VICTORIA

District: HOBBS

County
Name:

LEA

Field: GREGORY A

Legal: S: 33 T: 25S R: 37E

Well Type: GAS (PRODUCING)

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903742		122		
Pumping unit on well with rods in hole. No flowlines connected to wellhead. Location scraped and leveled. Took pictures. MW							
10/25/2005	Compliance Verification	Enforcement Action Follow-	iLWH0529848		102		
TANK BATTERY REMOVED, SITE CLEANED UP, OK!							
7/21/2005	Compliance Verification	Status Check	iSAD0520252		118		
7/21/05 CALLED XERIC SPOKE TO ROY PUGH; WELL WAS SHUT DOWN; BUDDY HILL INSPECTED AND FOUND PROBLEMS WITH BELTS BURNING? SEE BH'S INSPECTION.							
7/21/2005	Routine/Periodic	Normal Routine Activity	iLWH0520248		102	Y	103
BELTS OFF, MOTOR RUNNING, TURNED OFF @ ELECTRIC PANEL..CALLED SAD..ABANDONED TANK BATTERY ,SIGN SAYS "GREGORY 'A' TBATTERY #2". NEEDS TO REMOVED IF NOT IN USE..FIRST NOTICE							
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000701		114		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections

5

XERIC OIL & GAS CORP.

GREGORY A NO. 8

2310 FSL & 990 FEL (I)

SEC.33,T-25-S.R-37-E

LEA CO., NEW MEXICO

LEASE NO. LC-054667

GL.= 2999





13-Feb-09

Well Inspection History

API **30-025-11865-00-00**

Well Name && No.: **GREGORY C**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **GREGORY C**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903739		122		
		Rods stacked out in tubing. Location has been scraped and leveled. No flowline connected to wellhead. Well idle. Took pictures. MW					
3/17/2005	Routine/Periodic	Normal Routine Activity	iLWH0507659		102		
		WELL IS SHUT IN, NO T/A TEST SHOWN, CHECK WELL FILE.					
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000667		114		
	T/A						

Total Inspections

3

XERIC OIL & GAS CORP.

GREGORY C NO. 1
660 FNL & 1980 FWL (C)
SEC. 33, T-25-S, R-37-E
LEA CO., NEW MEXICO
LEASE NO. LC-054667
G.L. = 3004



13-Feb-09

Well Inspection History

API: **30-025-20491-00-00**

Well Name && No.: **GREGORY EL PASO FEDERAL**

Number:

Operator: **XERIC OIL & GAS CORP, VICTORIA**

District: **HOBBS**

County
Name:

LEA

Field: **GREGORY EL PASO FEDERAL**

Legal: **S: 33 T: 25S R: 37E**

Well Type: **GAS (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903741		122		
Well idle. No flowlines connected to well. Reda cable sticking out of wellhead. Location has been scraped and leveled. All debris from location pushed off on north side. Took pictures. MW							
8/27/2007	Routine/Periodic	Normal Routine Activity	iLWH0723954		102		
OK. All Equipment and Location in Good Shape.							
7/21/2005	Routine/Periodic	Normal Routine Activity	iLWH0520252		102		
OK. All Equipment and Location in Good Shape.							
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000698		114		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections

4

XERIC OIL & GAS CORPORATION

GREGORY EL PASO FED. NO. 1

SW/SE, SEC. 33-T25S-R37E

LEA CO., NM N.M. LOC 54667



EL PASO CORPORATION
EL PASO FED. NO. 1
SEC. 33-T25S-R37E
N.M. N.M. LOC 54667





13-Feb-09

Well Inspection History

API 30-025-11871-00-00

Well Name && No.: GREGORY EL PASO FEDERAL

Number:

Operator: XERIC OIL & GAS CORP, VICTORIA

District: HOBBS

County
Name:

LEA

Field: GREGORY EL PASO FEDERAL

Legal: S: 33 T: 25S R: 37E

Well Type: SALT WATER DISPOSAL WELL

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/6/2009	Compliance Verification	Normal Routine Activity	iMAW0903740		122		
	Well idle. No flowline connected to well. Took pictures. MW						
8/27/2007	Routine/Periodic	Normal Routine Activity	iLWH0723955		102		
	OK. All Equipment and Location in Good Shape.						
1/26/2006	Bradenhead	Normal Routine Activity	iSAD0602648		118		
	All Equipment and Location in Very Good Shape.						
7/1/2005	Routine/Periodic	Normal Routine Activity	iLWH0518259		102		
	OK. All Equipment and Location in Good Shape.						
1/4/2005	Pressure Test	Request/Complaint	iLWH0500458		102		
	P/T AFTER TBG. REPAIR. OK !						
12/28/2004	Pressure Test		iSAD0432253		114		
	OK. All Equipment and Location in Good Shape.						
12/30/2003	Bradenhead		iSAD0332937		102		
	A-OK. All Equipment and Location in Good Shape.						
12/4/2002	Bradenhead		iSAD0229835		102		
	A-OK. All Equipment and Location in Good Shape.						
1/18/2001	Bradenhead		iSAD0035543		113		
	OK. All Equipment and Location in Good Shape.						
3/23/2000	Salt Water Injection Well	Request/Complaint	iLWH0000452		102		
	CHECK FOR PAUL K..WELL IS ACTIVE.ON VACUUM @ ABOUT 1100 BPD.WATER						
2/9/2000	Routine/Periodic	Normal Routine Activity	iELG0000696		114		
	A-OK. All Equipment and Location in Good Shape.						
12/8/1999	MIT Witnessed - Other	Request/Complaint	iLWH0000233		102		
	A-OK. All Equipment and Location in Good Shape.						
12/4/1997	MIT Witnessed - Other		unk0011860		103		
12/2/1996	MIT Witnessed - Other		unk0011859		109		

Total Inspections

14

XERIC OIL & GAS CORP.

GREGORY EL PASO FED. #4 SWD

NE/SW, SEC. 33-T25S-R37E

LEA CO., NM N.M. LOC 54667



XERIC OIL & GAS CORP.

GREGORY EL PASO FED. #4 SWD

NE/SW, SEC. 33-T25S-R37E

LEA CO., NM N.M. LOC 54667

