

11-Aug-09

Well Inspection History

API Number: **30-025-28295-00-00** Well Name & No.: **POST**
 Operator: **PLATINUM EXPLORATION INC, CONRAD T** District: **HOBBS** County Name: **LEA**
 Field: **POST** Legal: **S: 1 T: 14S R: 37E**
 Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/27/2009	Compliance Verification	Status Check	iMGB0920861		119	Y	100 13
Idle Well (Rule 19.15.25.8). NEED TO RETURN WELL TO PROD., T/A OR P/A WELL. ELECTRICAL CONTROL PANEL LAYING ON GROUND. ELECTRIC METER REMOVED AND LINE FUSES DOWN. ALSO NEED SIGN WITH CURRENT INFORMATION. RULE 19.15.16.8. THIS IS 2ND LETTER OF NON-COMPLIANCE.							
6/24/2009	Routine/Periodic	Normal Routine Activity	iMGB0917558		119	Y	100 114
Idle Well (Rule 19.15.25.8). NEED TO RETURN TO PROD., T/A, OR P/A WELL. NO PROD REPORTED IN OVER 35 MONTHS. NEED TO INSTALL WELL SIGN (RULE 19.15.16.8). THIS IS 1ST LETTER OF NON-COMPLIANCE.							
6/23/2009	Routine/Periodic	Normal Routine Activity	iMGB0917456		119		
SURPLUS SUB PUMP CONTROL PANEL LAYING ON THE GROUND. NO PUMPING EQUIP. MGB.							
6/5/2009	Complaint Response	Normal Routine Activity	iSAD09156622		118		
TODD ROBERSON WANTED INSPECTED-CELLAR HAS FLUID; COMB. OF OIL & WATER; POSSIBLY LEAKING UNDERGROUND AND RISING TO SURFACE; TURN OVER TO ENVIRONMENTAL DEPT.? WAS INSPECTED IN 2007-RECORD PLACED ON WRONG WELL SHOULD HAVE BEEN POST #2 NOT POST #1?							
10/4/2001	Routine/Periodic	Normal Routine Activity	iBEP01277471	1/7/2002	111	Y	
Well appears to be idle, Check Prod. No well sign							

Total Inspections Performed: 5

Case 14380

OCD Exhibit 9