




Lynx Petroleum Cons., Inc.
 Bone Spring Structure/Iso
 CI ISO=10' CI Structure=50'

BEFORE THE OIL CONSERVATION DIVISION
 Santa Fe, New Mexico
 Case No. 14480 Exhibit No. 1
 Submitted by:
 LYNX PETROLEUM CONSULTANTS, INC.
 Hearing Date: June 10, 2010