

GP II ENERGY, INC.
LANGLIE JAL UNIT

LC-055546

DANGER

HYDROGEN SULFIDE
POISON GAS

NO SMOKING
NO SPARKS
NO OPEN FLAMES

LANGLIE JAL UNIT

Crystal
Archive
PAPER

No. 12202

NMOCID ID # 832236 BY: W Price #1
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. sec 5-Ts25s-R37e
Unreported system failure, tank overfloww est 400 bbl water, 60 bbl oil
per Chris Mitchell who was on-site.

Crystal
Archive
PAPER

1-069U 024



<No. 11>8

NMOCID ID # 832236 BY: W Price #3
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. sec 5-Ts25s-R37e
Pumphouse. oil & water on ground.
looking West.

NH-12RU 024

GP II ENERGY, INC.

LANGLIE JAL UNIT # 59 WIW
J-5-25S-37E
LEA COUNTY, NEW MEXICO
LC-055546

Mo. 19/00
NMOCD ID # 832237 BY: W Price #1
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. Location approx. 400 yds
south of INJ st.
1-03PM 027



CHG.130023

NMOCID ID # 832236 BY: W Price #2
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. sec 5-Ts25s-R37e
Water & Oil from pumphouse.

138U 024



Crystal
Archive
No. 29>005

NMOCD ID # 832237 BY: W Price #2
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. Location approx. 400 yds
south of INJ st. Oil saturated soil.

Crystal
Archive
14811 027



CMC-20
1600 027

NMOCD ID # 832237 BY: W Price #3
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. 400 yds south of INJ st. Oil
saturated soil. Looking NW.



Chc. 492007 364

NMOCID ID # 832237 BY: W Price #4
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. 400 yds south of INJ st. Oil
saturated soil. Looking NORTH.

1 027



440.58X001
21RU 027


NMOCID ID # 832237 BY: W Price #5
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. 400 yds south of INJ st. Oil
saturated soil. Looking East



Mo. 6A/811

NMOC ID # 832237 BY: W Price #6
Date/Time: FEB 19, 1998 4 pm
Site/Location: CP II Energy Inc.
Subject: N. INJ. St. J sec 5-Ts25s-R37e
Pumphouse. 400 yds south of INJ st. Oil
saturated soil. Looking North flow path.

178U 827



GP II ENERGY, INC.
SOUTH INJECTION STATION
LANGLIE JAL UNIT

A black rectangular sign with white text is positioned in the foreground. The sign is mounted on a post and has a reflective surface. The text is arranged in three lines. The background shows an industrial site with various structures and equipment.

QNo. 790813

NMOCID ID # 832237 BY: W Price #7
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: S INJ. St. I sec 8-Ts25s-R37e
Salt Water leak flowed into playa lake
SE of location.

25941 027

<Mo. 08/01

NMOCID ID # 832237 BY: W Price #8
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: S INJ. St. I sec 8-Ts25s-R37e
Salt Water leak flowed into playa lake
SE of location. Salt stains on ground.

N-208AU 027





10CD ID # 832237 BY: W Price #9
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: S INJ. St. I sec 8-Ts25s-R37e
Salt Water leak flowed into playa lake
E of location. Salt stains on ground.

Look NW



10CD ID # 832237 BY: W Price #10
ate/Time: FEB 19, 1998 4 pm
ite/Location: CP II Energy Inc.
ubject: S INJ. St. I sec 8-Ts25s-R37e
alt Water leak flowed into plays lake
E of location. Salt stains on ground.



OCD ID # 832237 BY: W Price #11
te/Time: FEB 19, 1998 4 pm
te/Location: GP II Energy Inc.
bject: S INJ. St. I sec 8-Ts25s-R37e
lt Water leak flowed into playa lake
of location. Salt stains on ground.



QNo. 128X02

NMOCID ID # 832237 BY: W Price #12
Date/Time: FEB 19, 1998 4 pm
Site/Location: GP II Energy Inc.
Subject: S INJ. St. I sec 8-Ts25s-R37e
Salt Water leak flowed into plays lake
SE of location. looking NW at Inj st.

1-1998 027



832237

(No. 139)026 36400 NNNNN-139U 027