

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|--|
| Name GP II ENERGY, INC. | Contact Elaine B. McCarty |
| Address P. O. Box 50682, Midland, TX 79710 | Telephone No. (915) 684-4748 |
| Facility Name Langlie Jal Unit | Facility Type Water Injection Plant |

| | | |
|--------------------------------|---------------|-----------|
| Surface Owner Becky Jo Doom | Mineral Owner | Lease No. |
|--------------------------------|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|---------------|
| Unit Letter G | Section 5 | Township 25S | Range 37E | Feet from the | North/South Line | Feet from the | East/West Line | County Lea |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|---------------|

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release Salt Water | Volume of Release Calc. by 2160 bbl. recovery | Volume Recovered 2160 bbl. |
| Source of Release Triplex injection pump | Date and Hour of Occurrence 3-7-98 4:00 AM | Date and Hour of Discovery 3-7-98 8:00 AM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Left message w/answering service for Charlie Perrin | |
| By Whom? Chris D. Mitchell | Date and Hour 3-7-98 1:00 PM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)


Describe Cause of Problem and Remedial Action Taken (Attach Additional Sheets If Necessary)

Stud in packing gland on rental pump broke.
Shut off lease. Call vacuum trucks.

Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets If Necessary)

Leak contained inside fenced area of injection plant.
Water removed by vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|------------------------------------|-------------------------|-----------------------------------|
| Signature  | OIL CONSERVATION DIVISION | | |
| Printed Name Chris D. Mitchell | Approved by District Supervisor | | |
| Title Field Representative | Approval Date: | Expiration Date: | |
| Date 3-18-98 | Phone 915/634-1750 | Conditions of Approval: | Attached <input type="checkbox"/> |

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action
OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|---------------------------------------|
| Name GP II ENERGY, INC. | Contact Elaine McCarty |
| Address P. O. Box 50682, Midland, TX 79710 | Telephone No. (915) 684-4748 EXT 5 |
| Facility Name Langlie Jal Unit | Facility Type Injection Plant |

| | | |
|--------------------------------|---------------|-----------|
| Surface Owner Becky Jo Doom | Mineral Owner | Lease No. |
|--------------------------------|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|--------|
| Unit Letter G | Section 5 | Township 25S | Range 37E | Feet from the | North/South Line | Feet from the | East/West Line | County |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|--------|

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release Salt water and oil | Volume of Release Calc. by 250 bbl. recovery | Volume Recovered 250 bbl. |
| Source of Release Storage tank | Date and Hour of Occurrence 2-20-98 12:00 PM | Date and Hour of Discovery 2-20-98 12:00 PM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Sylvia | |
| By Whom? Elaine McCarty | Date and Hour 2-20-98 2:10 PM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Hole formed in storage tank.
Back hoe (already on site from previous leak) dammed up around battery.
Called transport and vacuum trucks.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Leak contained within fenced area of injection plant. Transport trucks emptied tank of fluid. Vacuum trucks picked up fluid off of ground. Sundance Services hauled off contaminated dirt and caliche. Clean dirt and caliche hauled in and spread.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---------------------------------------|--|---|
| Signature <i>Chris D. Mitchell</i> | OIL CONSERVATION DIVISION | |
| Printed Name Chris D. Mitchell | Approved by District Supervisor <i>Wayne Price</i> | Expiry Date 8/01/98 |
| Title Field Representative | Approval Date 8/01/98 | Expiration Date |
| Date 3-4-98 | Phone (915) 634-1750 | Conditions of Approval Attached <input type="checkbox"/> |

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|---------------------------------------|
| Name GP II ENERGY, INC. | Contact Elaine McCarty |
| Address P. O. Box 50682, Midland, TX 79710 | Telephone No. (915) 684-4748 EXT 5 |
| Facility Name Langlie Jal Unit | Facility Type Injection Plant |

| | | |
|--------------------------------|---------------|-----------|
| Surface Owner Becky Jo Doom | Mineral Owner | Lease No. |
|--------------------------------|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|--------|
| Unit Letter G | Section 5 | Township 25S | Range 37E | Feet from the | North/South Line | Feet from the | East/West Line | County |
|------------------|--------------|-----------------|--------------|---------------|------------------|---------------|----------------|--------|

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release Salt water and oil | Volume of Release Calc. by 250 bbl. recovery | Volume Recovered 250 bbl. |
| Source of Release Storage tank | Date and Hour of Occurrence 2-20-98 12:00 PM | Date and Hour of Discovery 2-20-98 12:00 PM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Sylvia | |
| By Whom? Elaine McCarty | Date and Hour 2-20-98 2:10 PM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)


Describe Cause of Problem and Remedial Action Taken (Attach Additional Sheets If Necessary)

Hole formed in storage tank.
Back hoe (already on site from previous leak) dammed up around battery.
Called transport and vacuum trucks.

Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets If Necessary)

Leak contained within fenced area of injection plant. Transport trucks emptied tank of fluid. Vacuum trucks picked up fluid off of ground. Sundance Services hauled off contaminated dirt and caliche. Clean dirt and caliche hauled in and spread.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|------------------------------------|-----------------------------------|
| Signature  | OIL CONSERVATION DIVISION | |
| Printed Name Chris D. Mitchell | Approved by District Supervisor | |
| Title Field Representative | Approval Date: | Expiration Date: |
| Date 3-4-98 | Phone (915) 634-1750 | Conditions of Approval: |
| | | Attached <input type="checkbox"/> |