




ONL CONSERVATION DIVISION

CASE NUMBER

EXHIBIT

10

LRIC / CAPATAZ OPERATING

MARSHALL #1

Lea County, New Mexico and Gaines County, Texas

STRUCTURE MAP TOP OF DRINKARD POROSITY

Contour Interval = 50'

Date: May, 2001

Geology by: John Worrall

LRIC / Capataz Location

Drinkard Producer

Tested Non Commercial this Zone

Not Deep Enough

Not Available

No Log this Interval

Top of Porosity is Nadline Zone

Top of Porosity is House Zone

○

●

△

N

NA

NLT1

-3500 Nd

-3500 H