

September 13, 1968

San Simon #1 Barron - Sec 8, T 21S,
R 34E. West of Wilson Pool.



September 13, 1968

Jeff Davis water well - Sec 1 T21S,
R 34E, North west of Wilson Pool



September 13, 1968

San Simon #1 - North Well - Sec 30,
T 21S, R 35E, this well is located
South East of the Wilson Pool



September 13, 1968

San Simon #1 North Well - Sec 30, T21S
R 35E, this well is located South
East of the Wilson Pool



September 13, 1968

Wilson Oil Company camp. The view
is to the South east which shows
a mound of caliche at pit #5.

OLIO REVIATION MISSION

El Paso, New Mexico

Exhibit No. 3859

Case No. 3859



9

September 13, 1968

View of Wilson Oil Company property looking west across Sec 13, T 21S, R 34E. In the foreground to the right is pit #2, in the background in the center is pit #1. Water well #5 is shown by overhead water tank with abandoned pumper's house location on the extreme left.



September 13, 1968

San Simon #1 North well Sec 30,
T 21S, R 35E, this well is located
South East of the Wilson Pool



September 13, 1968

Wilson Oil Company camp, viewed from
the east with Wilson G battery in the
right of the view. This photograph
looks across pit #7.



September 13, 1968

View of Wilson Oil Company camp
looking to the southwest which shows
pump house for Wilson water well #1



September 13, 1968

Wilson Oil Company Camp viewed from
the west showing Water Well #2 in the
foreground.



September 13, 1968

Wilson Oil Company camp. The view
is to the southeast which shows a
mound of caliche at pit #5.

