

Schlumberger		SIDEWALL NEUTRON POROSITY LOG	
COUNTY LEA FIELD DICKENSON LOCATION SANTA FE #2 WELL COMPANY FLAG REDFERN OIL	COMPANY FLAG REDFERN OIL COMPANY		
	WELL SANTA FE #2		
	FIELD DICKENSON		
	COUNTY LEA STATE NEW MEXICO		
Location 660' FNL & 660' FWL		API Serial No.	Other Services: OLL
Sec. 35 Twp. 10-S Rge. 36-E			
Permanent Datum: G.L.		Elev. 3991	Elev. K.B. 4002
Log Measured From: K.B.		11 Ft. Above Perm. Datum	D.F. 4001
Drilling Measured From: K.B.			G.L. 3991
Date	4-4-76		
Run No.	ONE		
Depth-Driller	5085		
Depth-Logger	5090		
Bottom Log Interval	5088		
Top Log Interval	0		
Casing-Driller	8 5/8 @ 411	@	@
Casing-Logger	416		
Bit Size	7 7/8		
Type Fluid in Hole	SALT MUD		
Dens. Visc.	10 49		
pH Fluid Loss	- 5.8 ml		
Source of Sample	PIT		
Rm @ Meas. Temp.	.073 @ 68°F		
Rmf @ Meas. Temp.	.053 @ 68°F		
Rmc @ Meas. Temp.	.105 @ 68°F		
Source Rmf Rmc	C C		
Rm @ BHT	.05 @ 107°F		
Circulation Stop	0300 4-5		
Logger on Bottom	0700 4-5		
Max. Rec. Temp.	107°F		
Equip. Location	7629 HOBBS		
Recorded By	CAMPAIGN		
Witnessed By	CARTER		

Reproduced By
Electrical Log Services, Inc.
Midland, Texas 79701

REFERENCE W 45455

10 COMPLETION RECORD

6446

SPUD DATE

COMP DATE

DST RECORD

API NO. 30-025-25241