


Schlumberger		COMPENSATED NEUTRON-LITHO-DENSITY			
COMPANY		AVON ENERGY CORPORATION			
WELL		TURNER "B" NO. 97			
FIELD		GRAYBURG JACKSON			
COUNTY		EDDY	STATE NEW MEXICO		
LOCATION		2670' FNL & 1200' FEL			
UNIT		H			
API SERIAL NO.		20	TWP. 17-S	RANGE 31-E	Other Services: LDT/CNL DLT/RXO CYBER AMS LOCKET ARCHIVE
Permanent Datum		GL	Sea. 110 F	3711.0 F	Elev.: K.B. 3722.0 F
Log Measured From		K3	D.F. G.L. 3711.0 F		
Drilling Measured From		K3			
Date		03-MAR-1991			
Run No.		ONE			
Depth Order		3800.0 F			
Depth Logger (Sohl.)		3787.0 F			
Btm. Log Interval		3754.0 F			
Top Log Interval		0.0 F			
Casing-Order		8 5/8 @ 1366.0 F			
Casing-Logger		1370.0 F			
Bit Size		7 7/8"			
Type Fluid in Hole		BRINE			
Dens. Visc.		10.40 LB/G 28.0 S			
pH Fld. Loss		10.0			
Source of Sample		PT			
Rm @ Meas. Temp.		066 OHMM @ 87.0 DEGF			
Rmt @ Meas. Temp.					
Rms @ Meas. Temp.					
Source: Rmt Rms					
Rm @ 80°F		066 OHMM @ 80.0 DEGF			
Correlation Index		1790			
Logger on Bottom		SEE LOG			
Max. Rec. Temp.		88.0 DEGF			
Equip. Location		8328 ROSWELL			
Recorded By		PAT SULLIVAN			
Witnessed By		SETZLER			



GRAYBURG

LOCO HILLS

METEX

SQUARE LAKE

PREMIER

SAN ANDRES

VACUUM

LOVINGTON

JACKSON

EXAMINER CATANACH
OIL CONSERVATION DIVISION
Avon EXHIBIT NO. 3
CASE NO. 10290

EXHIBIT

TYPE LOG

GRAYBURG JACKSON POOL
EDDY COUNTY, NEW MEXICO

AVON ENERGY CORP.
415 West Wall Suite 1810
Midland, Texas