

OIL PROCESSING, INC.

Inventory as of May 13, 1986

This treating plant is located approximately five miles south of Monument on Hwy 8 approximately 200 yards west of the highway

South Side of Road

- 9 - 500 bbl tanks w/walkway attached
- 1 - 300 bbls storage tank
- 3 - melting pits buried below ground
- 1 - cement foundation approximately 30' x 60' - building has been removed
- 1 - cement foundation approximately 10' x 12' - building has been removed
- 1 - assortment of tanks, barrels, junk, and old bus
- 1 - pile of oily dirt covering approximately 1/3 acre

North Side of Road

- 1 - building - 10' x 20'
- 1 - 4' x 20' heater treater - in use
- 4 - 4' x 20' heater treating in NW corner laying down - not in use
- 1 - 10' x 10' building
- 14 - tanks - 500 bbl & 750 bbl - all connected w/walkway in center of location
- 7 - tanks on east edge of location - 250 & 500 bbls
- 4 - tanks on north side of location - 3/250 & 1/750 bbls
- 1 - frac tank on front side of location
- 1 - assorted pipe & junk in NW corner



Oil Processing 5-13-86



Oil Processing 5-13-86



Case 8983 Ex. 1-A



Case 8983 Ex. 1-B



Case 8983 Ex. 1-C



Case 8983 Ex 1-D



Case 8983 Ex 1-E



Case 8983 Ex 1-F

PS Form 3811, July 1983 447-845

DOMESTIC RETURN RECEIPT

SENDER: Complete items 1, 2, 3 and 4.

Put your address in the "RETURN TO" space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for service(s) requested.

1. ☒ Show to whom, date and address of delivery.

2. ☐ Restricted Delivery.

3. Article Addressed to:
McCleskey, Harriger, Brazill
P. O. Drawer 6170
Lubbock, Texas 79493

4. Type of Service: Article Number
☐ Registered ☐ Insured
☒ Certified ☐ COD P 612 458 173
☐ Express Mail

Always obtain signature of addressee or agent and **DATE DELIVERED.**

5. Signature - Addressee
X

6. Signature - Agent
X *S. Stokes*

7. Date of Delivery

8. Addressee's Address (ONLY if requested and fee paid)

P 612 458 173

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED
NOT FOR INTERNATIONAL MAIL

(See Reverse)

PS Form 3800, Feb. 1982

★ U.S.G.P.O. 1983-403-517

Sent to McCleskey, Harriger, etc.	
Street and No. P. O. Drawer 6170	
P.O., State and ZIP Code Lubbock, Texas 79493	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to whom and Date Delivered	
Return receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

PS Form 3800, Feb. 1982

★ U.S.G.P.O. 1983-403-517

Sent to The Travelers Companies	
Street and No. P. O. Box 4356	
P.O., State and ZIP Code Englewood, Colorado 80155	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to whom and Date Delivered	
Return receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

P 612 458 175

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED
NOT FOR INTERNATIONAL MAIL

(See Reverse)



TONEY ANAYA
GOVERNOR

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION

50 YEARS



1935 - 1985

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE, NEW MEXICO 87501
(505) 827-5800

September 2, 1986

CERTIFIED - RETURN
RECEIPT REQUESTED

McCleskey, Harriger, Brazill & Graf
Attorneys at Law
P. O. Drawer 6170
Lubbock, Texas 79493

The Travelers Companies
P. O. Box 4356
Englewood, Colorado 80155

Re: Oil Processing, Inc.
Treating Plant Bond
Lea County

Gentlemen:

Enclosed is a copy of the advertisement of the Examiner Hearing to be held on Wednesday, September 17, 1986, at 8:15 a.m. in the Oil Conservation Division Conference Room, State Land Office Building, Santa Fe, New Mexico. Case 8983 concerns the above captioned subject matter.

Sincerely,

JEFFREY TAYLOR
General Counsel

JT/fd
enc.

BEFORE EXAMINER STOGNER	
OIL CONSERVATION DIVISION	
010	EXHIBIT NO. 2
CASE NO.	8983

E

Tanks, Pipes, Bombs
a Bus etc.

§

Q

10/15/50

0
H
I
X
20

7-10-18
 250 + 500
 3 of each

Oil Processing

A hand-drawn diagram of a rectangular building layout. The layout includes the following rooms and labels:

- Top Room:** A room at the top with two circles inside, labeled "250" and "250".
- Top-Right Room:** A room on the top right with two circles inside, labeled "250" and "250".
- Right Room:** A room on the right side with two circles inside, labeled "250" and "250".
- Bottom-Right Room:** A room at the bottom right with two circles inside, labeled "250" and "250".
- Bottom Room:** A room at the bottom with two circles inside, labeled "250" and "250".
- Left Room:** A room on the left side with two circles inside, labeled "250" and "250".
- Top-Left Room:** A room at the top left with two circles inside, labeled "250" and "250".
- Central Room:** A room in the center with a square and a circle inside, labeled "250" and "250".
- Bottom-Left Room:** A room at the bottom left with two circles inside, labeled "250" and "250".
- Left Wallway:** A narrow passage on the left side, labeled "Left wallway".
- Top Wallway:** A narrow passage at the top, labeled "Top wallway".
- Right Wallway:** A narrow passage on the right side, labeled "Right wallway".
- Bottom Wallway:** A narrow passage at the bottom, labeled "Bottom wallway".

430
Cane
Cane

Bath N^o 100 = 600 April 5 57 0711