




SKELLY OIL COMPANY - EXH. - 1
ENGINEERING REPORT
HUEFAPANTO UNIT
SAN JUAN COUNTY, NEW MEXICO

MAP SHOWING
PICTURED CLIFFS POOLS
SHOWING INITIAL SHUT-IN PRESSURES

WELLS COMPARED IN REPORT

RIIW

RIOW