

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-021- 20567 20568
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Libby Minerals LLC 2031
8. Well Number 8-2-M
9. OGRID Number 251905
10. Pool name or Wildcat Bravo Dome 96010

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other CO2 Well

2. Name of Operator
Reliant Exploration & Production, LLC.

3. Address of Operator
10817 West County Road 60 Midland, TX 79707

4. Well Location
Unit Letter M: 660 feet from the South line and 1070 feet from the West line
Section 8 Township 20 N Range 31 E NMPM County Harding

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4553.6

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	P AND A <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPL <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Vance Vanderburg TITLE Manager DATE 12-12-13
Type or print name Vance Vanderburg E-mail address: vance.vanderburg@esens Telephone No. 452-555-7055
For State Use Only
APPROVED BY: Ed Martin TITLE **DISTRICT SUPERVISOR** DATE 12/20/2013
Conditions of Approval (if any):

Libby Minerals LLC 2031 8-2-M

10/23/13

(16:00)MIRU Renegade Wireline. Perforate 1480' – 1500' @ 4 SPF. RD Renegade Wireline.

10/25/13

(14:00) MIRU Borderline Well Service. 3 Swab runs fluid level down to 800'. Made 6 more runs fluid level still at 800'. Waited 15 minutes. Fluid level at 700'. Made 16 more swab runs +/- 120 bbls fluid.

(18:00) Shut well in.

10/26/13

(08:00) Swabbed 240 bbls of fluid. Level still at 800'. Shut in. MDRO Borderline well Service.

10/29/13

MIRU Renegade Wireline. RIH with bridge plug set @ 1450'. Perforate 1080' – 1110' @ 4 SPF. RD Renegade Wireline.

10/31/11

(08:00) MIRU Borderline Well Service. Made Swab run. fluid level @ 800'. Made 17 more runs to 1450' fluid level never fell below 1050'. Waited 15 minutes. Fluid level at 700'. Cuaght 3 water samples.

(15:00) RDMO Borderline Well service. Shut well in.

11/12/13

MIRU Renegade Wireline. RIH with bridge plug set @ 1000'. Perforate 840' – 870' @ 4 SPF. RD Renegade Wireline.

MIRU Borderline Well Service. Swabbed hole dry. MDRO Borderline.

RECEIVED OGD

2013 DEC 17 P 3: 21



December 12, 2013

Mr. Ed Martin
District IV Supervisor
New Mexico Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505

Re: Form C-103

Dear Mr. Martin:

Please find enclosed for your approval Form C-103 for the following well;

Libby Minerals LLC 2031 8-2-M.

Please send the approved 103's to my attention at the following address;

7714 Georgetown Drive

Amarillo, TX 79119

Please let me know if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Vance Vanderburg". The signature is stylized with a large, sweeping "V" and a long, horizontal stroke.

Vance Vanderburg
vance@reliantholdingsltd.com
432-559-7085