

APR 2 1 2020

RECEIVED APR 2 1 2020		
State of New Maximum Office State of New Maximum Office Form C-103		
District 1	erals and Nataval Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	Δ	WELL API NO 30-015-29525
District II 811 S. First St., Artesia, EMNRD-OCDARIES SERVATION DIVISION		5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410		STATE S FEE
District IV San	ta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Medano State
1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other		8. Well Number 002
2. Name of Operator		9. OGRID Number
Penroc Oil Corporation		17213 10. Pool name or Wildcat
3. Address of Operator PO Box 2769, Hobbs, NM 88241		Livingston Ridge; Delaware
4. Well Location		Livingston Ridge, Delaware
Unit Letter N: 660 feet from the South line and 1980 feet from the West line		
Section 36 Township 22S Range 31E NMPM County Eddy		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3460		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: All pits have been remediated in compliance with O		eady for OCD inspection after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME A FACE NAME WELL NUMBER ADAMANER OF A PROPERTY OF A PROPER		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Power pole\lines not removed Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. flow line not removed		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
to be removed.) **Itash on location and in pasture not removed** **All other environmental concerns have been addressed as per OCD rules.**		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE TITLE President DATE 04/09/2020		
SIGNATURE		
TYPE OR PRINT NAME M.Y. Merchant E-MAIL: mymerch@penrocoil.com PHONE: 575-492-1236		
For State Use Only		
A DDD OVED DV	DENIED	DATE 9C 5/1/2020
APPROVED BY:Conditions of Approval (if any):	DEITIED	DATE_gc 5/1/2020