Submit One Copy To Appropriate District Office <u>District I</u>	Ctata of Marri Marrian		EMNRD-OCD ARTESIA REC'D: 4/28/2020 Form C-103 Revised November 3, 2011			
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION			WELL API NO. 30-015-26980		
811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	strict III 1220 South St. Francis Dr.			5. Indicate Type of Lease STATE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87		6. State Oil & Gas Lease No. K-6385			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Dee 36 SE Sta	7. Lease Name or Unit Agreement Name Dee 36 SE State 8. Well Number		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Numb			
2. Name of Operator				9. OGRID Number 7377		
EOG Y Resources, Inc. 3. Address of Operator				10. Pool name or Wildcat		
104 South Fourth Street, Artesia, NM 88210			N. Seven Rive	N. Seven Rivers; Glorieta – Yeso, North		
4. Well Location Unit Letter I 1820 feet from the Couth line and 800 feet from the Feet line						
Unit Letter <u>I</u> : <u>1830</u> feet from the <u>South</u> line and <u>890</u> feet from the <u>East</u> line Section 36 Township 19S Range 24E NMPM Eddy County						
	. Elevation (Show whether DR,	, RKB, RT, GR, e		<u>Jaay</u>		
3589' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
,^						
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					OF: NG CASING □	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A						
PULL OR ALTER CASING MI	ULTIPLE COMPL	CASING/CEME	ENT JOB]		
OTHER: Description Location Location						
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR						
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR						
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. Buried flow line beside road not properly abandoned						
Buried flow line beside road not properly abandoned The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and						
other production equipment. Buried power lines removed. ☐ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with						
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. Trash on location & in pasture removed.						
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have						
to be removed.) Risers besides road to location are active (Attached Lucid email). All other environmental concerns have been addressed as per OCD rules.						
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-						
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Resources gas system. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well						
location, except for utility's distribution infrastructure.						
When all work has been completed, return this form to the appropriate District office to schedule an inspection.						
SIGNATURE Quality	11 1	Environmental	•		4/26/2020	
SIGNATURE	111LE	Elivironmental	Supervisor	DATE_	4/26/2020	
TYPE OR PRINT NAME: Robert Ashe For State Use Only	E-MAIL:	Robert Asher	@eogresources.con	n PHONE:	<u>575-748-4217</u>	
·	DENIED				E 17 10005	
APPROVED BY:Conditions of Approval (if any):	DEIVIED			DATE_	5/7/2020	

From: Jason Fuentes < JFuentes@lucid-energy.com>

Sent: Friday, February 7, 2020 12:51 PM

To: Bob Asher <Bob_Asher@eogresources.com> **Cc:** Frankie Soto <FSoto@lucid-energy.com>

Subject: Dee State 36

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Lucid is requesting the risers at the Dee 36SE State #5 & #6 remain in place due to the fact that it is attached to an active pipeline that remains in gas gathering service. Lucid will install a pipe around the riser for security. If the system volumes allow for removal in the future Lucid will cut/cap the riser below grade.

Thank you,

Jason S. Fuentes Sr. Director of Pipeline Operations



201 S. 4th Street Artesia, NM Office 575.810.6136 | Cell 575.365.8939 <u>ifuentes@lucid-energy.com</u> | <u>www.lucid-energy.com</u>