OCD – Artesia – REC'D 6/10/2020

Office	te of New Mexic		Form C-103 Revised November 3, 2011		
District II	nerals and Natural Resources		WELL API NO. 30-005-21083		
811 S. First St., Artesia, NM 88210 OIL CONS	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec. NM 87410			STATE 🗡 🛛	FEE	
1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			17847 7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		BACK TO A	CAUDILL		
PROPOSALS.) 1. Type of Well: XOil Well Gas Well Other			8. Well Number 002		
2. Name of Operator RELIANCE ENERGY, INC.			9. OGRID Number 149441		
3. Address of Operator			10. Pool name or Wildcat		
300 N. MARIENFELD, STE 1100, MIDLAND TX 79701			Caprock, Queen		
4. Well Location					
Unit Letter <u>D</u> : <u>330</u> feet from the <u>N</u> line and <u>750</u> feet from the <u>W</u> line Section <u>34</u> Township <u>135</u> Range <u>31F</u> NMPM County Chaves					
Section _34Township _13S_Range _31ENMPMCounty _Chaves           11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
4267' GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB					
OTHER:		l ocation is read	ly for OCD inspection of	tor DS A	
OTHER:       Image: Location is ready for OCD inspection after P&A         Image: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.					
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the</li> </ul>					
- a shows the					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and					
other production equipment. Flow lines not removed Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with					
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed					
from lease and well location. Buried cable on west side of location not removed All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have					
to be removed.) (Trash on location and in pasture not removed)					
All other environmental concerns have been addressed as per OCD rules.					
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.					
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well					
location, except for utility's distribution infrastructure.					
When all work has been completed, return this form to the appropriate District office to schedule an inspection.					
SIGNATURE Botsy Luna	TITLE Rec	gulatory Manager	DATE	6/09/2020	
TYPE OR PRINT NAME Betsy Luna For State Use Only	E-MAIL: bl	una@reimid.com	PHONE:	432-683-4816	
APPROVED BY:	DENIED		DATE	gc 6/18/2020	