ALL ABOVE GROUND FLOW LINES MUST BE REMOVED

ALL BURIED LINES MUST BE PROPERLY ABANDONED

OCD - Artesia - REC'D 6/10/2020

Submit One Copy To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-005-63303	
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		Indicate Type of Lease STATE X FEE G. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			26828	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name WILLOW SPRING 19 STATE	
Type of Well: Oil Well			8. Well Number 002	
RELIANCE ENERGY, INC.			9. OGRID Number 149441	
3. Address of Operator			10. Pool name or Wildcat	
300 N. MARIENFELD, STE 1100, MIDLAND TX 79701 4. Well Location			Pecos Slope; ABO (Gas)	
	feet from the _S _line and		line	
Section 19 Township 4S Range the 25E NMPM Chaves County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3919' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A DULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
OTHER:				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMP	ED ON THE MARKER'S S	URFACE.		•
The location has been leveled as other production equipment.	lines not removed			low lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. Buried plastic liner not removed All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
Trash and co	ncrete blocks not remove	e <mark>d</mark>	ved. (Foured onsite concrete bas	ses do not nave
All other environmental concerns	have been addressed as per (OCD rules.	All fluids have been non	C
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
If this is a one-well lease or last relocation, except for utility's distribution	maining well on lease: all ele n infrastructure.	ectrical service poles and	l lines have been removed from	lease and well
When all work has been completed, re	turn this form to the appropri	ate District office to scho	edule an inspection.	
SIGNATURE Retsey L	una TITLI	Regulatory Manag	erDATE6/	09/2020
TYPE OR PRINT NAME Betsy Lu For State Use Only	ina E-MA	IL: <u>bluna@reimid.co</u>	PHONE: 43	2-683-4816
APPROVED BY:	DEN	ED	DATE OF	6/17/2020