Office	State of New Mexico		Form C-103	
<u>District I</u> Energy, Miner 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.	
District II 811 S. First St., Artesia, NM 88210 OIL CONSE	OIL CONSERVATION DIVISION		30-015-2835 5. Indicate Typ	
District III 1220 So	1220 South St. Francis Dr.		STATE	X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> Santa	Santa Fe, NM 87505			Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)			Remuda Basin State	
1. Type of Well: X Oil Well Gas Well Other			8. Well Number <sub>009</sub>	
2. Name of Operator			9. OGRID Number	
XTO Energy, Inc.  3. Address of Operator			005380 10. Pool name or Wildcat	
•				
6401 Holiday Hill Road, Bldg 5, Midland, TX 79707 Nash Draw; Delaware 4. Well Location				
Unit Letter_N _:_ 660feet from the South line and 1750 feet from the West line				
Section 30 Township 23S Range 30E NMPM County Eddy				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3071' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK				ALTERING CASING
TEMPORARILY ABANDON				P AND A
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB				
OTHER:		✓ Location is r	andy for OCD inc	enaction ofter DSA
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
ODED ATOD NAME I FACE NAME WELL NUMBED ADIAUMDED OLIADTED/OLIADTED LOCATION OD				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Buried trash on N side of location				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. Flow lines and buried flow lines not removed  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
<del>_</del> ,,				
to be removed.) Power poles / power lines not removed  All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. Trash on location, in pasture, in brush and on road to location not removed  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
10-10-10-10-10-10-10-10-10-10-10-10-10-1				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
al Miller				
SIGNATURE	TITLEEr	nvironmental Co	ordinator	DATE <u>6/9/2020</u>
THE OF THE PROPERTY.	<b></b>			PVIOVE
TYPE OR PRINT NAME Amy C. Ruth	E-MAIL: _	amy_ruth@xtoei	nergy.com	PHONE: <u>575-689-3380</u>
For State Use Only				
APPROVED BY:	DENIE	)		DATE_gc6/17/2020