Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505  SUNDRY NOTICES AND DEPORTS ON WERE AS	Form C-103 Revised November 3, 2011 WELL API NO. 30-015-36200  5. Indicate Type of Lease STATE X FEE   6. State Oil & Gas Lease No. 49107
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: XOil Well Gas Well Other	7. Lease Name or Unit Agreement Name  Horned Toad 36 State  8. Well Number 3H
XTO Permian Operating, LLC  3. Address of Operator  6401 Holiday Hill Road, Bldg 5, Midland, TX 79707  4. Well Location	9. OGRID Number 373075 10. Pool name or Wildcat Nash Draw (Delaware/BS/Avalon SD)
Unit Letter_G :_ 1881 _ feet from the North line and 2225 feet from the East line  Section _ 36 _ Township _ 24S _ Range _ 29E _ NMPM County _ Eddy  11. Elevation (Show whether DR, RKB, RT, GR, etc.)  3113' GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   COMMENCE DRILLING OPNS.   P AND A   CASING/CEMENT JOB   CASING/CEMENT JOB	
OTHER:    D   Location is ready for OCD inspection after P&A	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below grown If this is a one-well lease or last remaining well on lease, the battery and pit location OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location.  Berm around location not removed	ment and Cable in Arroyos not removed. N side bund level. s) have been remediated in compliance with duction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)  Concrete, Cables and Buried Trash in Arroyos not removed. S Side  All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. Flow lines, buried flow lines and concrete not removed. S side  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.  Photos available in Well Files - Well Inspections	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.  SIGNATURE  TITLE Environmental Coordinator DATE 7/28/2020	
TYPE OR PRINT NAME Amy C. Ruth E-MAIL: amy ruth@xto	
APPROVED BY: DENIED	DATE gc 7/28/2020