	OCD – REC'D 8/21/2020
Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resource	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-015-23503
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISIO	N 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO .	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	1
2. Name of Operator Chevron USA Inc.	9. OGRID Number 4323
3. Address of Operator	10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 79706	N. Illinois Camp Morrow
4. Well Location:	
Unit Letter_H_:2310_feet from the <u>NORTH</u> line and <u>990</u> feet from the	EAST line
Section <u>25</u> Township <u>18-S</u> Range <u>28-E</u> NMPM County	
11. Elevation (Show whether DR, RKB, RT, C 3590' GL	GR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or O	ther Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/C	EMENT JOB
OTHER:	on is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. Meter house / Meter run not removed - shows to be for this well	
\square All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE <u>Katherine</u> PapageorgeTITLEDecommissioning Project ManagerDATE8.21.20	
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only	

DENIED

APPROVED BY:_

____DATE__gc__9/2/2020