From: McClure, Dean, EMNRD
To: "Rowell, Chery!"

 Subject:
 RE: Nash Unit 302H well file (30-015-45501)

 Date:
 Wednesday, September 16, 2020 3:08:00 PM

Attachments: image001.png

I have it accepted now, thanks.

Dean McClure
Petroleum Engineer, Oil Conservation Division
New Mexico Energy, Minerals and Natural Resources Department
(505) 469-8211

From: Rowell, Cheryl_Rowell@xtoenergy.com>

Sent: Wednesday, September 16, 2020 2:43 PM

To: McClure, Dean, EMNRD < Dean. McClure@state.nm.us> **Subject:** [EXT] RE: Nash Unit 302H well file (30-015-45501)

Dean,

Yes a CBL was run. I'm sorry the files were mis-named our log files. I will upload the CBL now.

Regards, Cheryl

Cheryl Rowell

Regulatory Coordinator



An **ExxonMobil** Subsidiary

432-218-3754

From: McClure, Dean, EMNRD [mailto:Dean.McClure@state.nm.us]

Sent: Wednesday, September 16, 2020 3:22 PM **To:** Rowell, Cheryl < <u>Cheryl_Rowell@xtoenergy.com</u>> **Subject:** RE: Nash Unit 302H well file (30-015-45501)

External Email - Think Before You Click

Hello Cheryl,

This email will be sufficient.

Regarding the logs, I do see the log with caliber, gamma ray, and collar locator tracks on it; however, do you know if a cement bond log was ran on this well?

Dean McClure
Petroleum Engineer, Oil Conservation Division
New Mexico Energy, Minerals and Natural Resources Department
(505) 469-8211

From: Rowell, Cheryl < <u>Cheryl_Rowell@xtoenergy.com</u>>

Sent: Wednesday, September 16, 2020 2:15 PM

To: McClure, Dean, EMNRD < <u>Dean.McClure@state.nm.us</u>> **Subject:** [EXT] RE: Nash Unit 302H well file (30-015-45501)

Dean,

Yes the ready date should be 2/27/20, my mistake.

I have uploaded the RCB/GR/CCL.

Do you want me to upload the attached As Drilled Plat and Certified Directional Survey to E-docs? Or is this sufficient?

Regards, Cheryl

Cheryl Rowell

Regulatory Coordinator



An **ExxonMobil** Subsidiary

432-218-3754

From: McClure, Dean, EMNRD [mailto:Dean.McClure@state.nm.us]

Sent: Wednesday, September 16, 2020 2:53 PM **To:** Rowell, Cheryl < Cheryl_Rowell@xtoenergy.com **Subject:** Nash Unit 302H well file (30-015-45501)

External Email - Think Before You Click

Hello Ms. Rowell,

I am reviewing the well file for Nash Unit #302H (30-015-45501) operated by XTO Energy, Inc. (5380).

Please submit the as drilled C-102 and directional survey for this well.

The ready date on the C-104 is incorrect. I assume the intended ready date is 2/27/20 rather than 2/27/19. Please confirm the date for me.

Additionally, reference was initially made to a CBL being run. Was this the case; if so, please submit it.

Dean McClure Petroleum Engineer, Oil Conservation Division New Mexico Energy, Minerals and Natural Resources Department (505) 469-8211