


# State Of New Mexico

## Energy, Minerals and Natural Resources Department

---

**Michelle Lujan Grisham**  
Governor  
**Sarah Cottrell Propst**  
Cabinet Secretary  
**Todd E. Leahy, JD, PhD**  
Deputy Cabinet Secretary

**Adrienne Sandoval**  
Division Director



**"Response Required - Deadline  
Enclosed"**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

21-Sep-20

**CFM OIL, LLC**  
P.O. Box 1176  
Artesia, NM 88210

**LETTER OF VIOLATION - Field Inspection**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***

[30-015-00237] WILLIAMS #005

OGRID: 280554

C-25-18S-26E 990 FNL 1980 FWL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
8/20/2020	Routine Inspection	[CZH] Chad Hensley	12/21/2020	iCZH2023332928


**Violations:**

Rule	Violation
19.15.18.16 Tanks, Oil Tanks, Fire Walls and Tank Identification	Tank identification missing or needs repaired
<b>Comment:</b> WELL SIGN NOT VISIBLE ON LOCATION.	
19.15.10.8 Safety Procedures for Drilling and Production	Substandard Equipment and/or Needs Repair
<b>Comment:</b> STUFFING BOX LEAKING.	
19.15.10.8 Safety Procedures for Drilling and Production	General Housekeeping Required
<b>Comment:</b> STAINING AROUND WH.	

---

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

---

Oil Conservation Division \* 811 S. First St. \* Artesia, NM 88210  
Phone: 575-748-1283 \* Fax: 575-748-9720 \* [www.emnrd.state.nm.us](http://www.emnrd.state.nm.us)

**From:** [Hensley, Chad, EMNRD](mailto:Hensley.Chad.EMNRD)  
**To:** [cfmoilcomp1176@hotmail.com](mailto:cfmoilcomp1176@hotmail.com)  
**Cc:** [lesliepatterson@msn.com](mailto:lesliepatterson@msn.com)  
**Subject:** Letters of Violation  
**Date:** Monday, September 21, 2020 2:58:00 PM  
**Attachments:** [3001500238 9-21-20 CFM LOV.pdf](#)  
[3001500318 9-21-20 CFM LOV.pdf](#)  
[3001500319 9-21-20 CFM LOV.pdf](#)  
[3001500235 9-21-20 CFM LOV.pdf](#)  
[3001500237 9-21-20 CFM LOV.pdf](#)

---

Louis Fulton,

Attached is the Letter of Violation(LOV) for the following wells:

Williams #2

Williams #3

Williams #5

Williams #6

McCall #1

If you have any questions feel free to contact me on my cell.

Thank you,

Chad Hensley  
Compliance Officer  
Artesia OCD  
Office: 575-748-1283 x 112  
Cell: 575-703-1723

