

District II - Artesia
 811 S. 1st Street, Artesia, NM 88210
 Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Oxy		API Number 30-015-27627	
Property Name S.D.S 11 Federal			Well No. # 001

Surface Location

Ul. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
F	11	24S	31E	2090		1980		Eddy

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES (NO)	ENJ (SWD)	OIL GAS	10-13-20

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	1155
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WIR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

MIT
A - Puff Gas
D - nothing

Accepted for record test not witnessed
 NMOCD DS 12-4-2020

Signature: _____	OIL CONSERVATION DIVISION	
Printed name: Reggie House	Entered	_____
Title: Production Tech II	Re-test	_____
E-mail Address: reggie-house@oxy.com		
Date: 10-13-20	Phone: 575-942-0363	
Signature: Reggie House	Witness: _____	