

District II - Artesia

811 S. 1st Street, Artesia, NM 88210
 Phone: (575) 748-1283 - Fax: (575)-748-9720

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Devon Energy Production Co. LP		API Number 30-015-32274	
Property Name BURTON FLAT DEEP UNIT		Well No. 44	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
F	3	21S	27E	3555	S	1660	W	EDDY

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES <input type="radio"/> NO <input checked="" type="radio"/>	YES <input type="radio"/> NO <input checked="" type="radio"/>	INJ <input type="radio"/> SWD <input checked="" type="radio"/>	OIL <input type="radio"/> GAS <input type="radio"/>	10-27-2020

OBSERVED DATA

	(A) Surf-Intern.	(B) Intern. (1)	(C) Intern. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	-	20 #	0	295
Flow Characteristics				VACUUM	
Puff	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR. <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

- A) SMALL POOF, NO FLUID
- C) 20# PSI, BLEW RIGHT DOWN, DID NOT CONTINUE TO BLOW, NO FLUID.
- D) ON A VACUUM

Accepted for record test not witnessed
 NMOCD DS 12-4-2020

Signature: Denise Menoud 575-748-5544	OIL CONSERVATION DIVISION
Printed name: Danny Smolik	Entered RBDMS
Title: Compliance Office 0	Re-test
E-mail Address: danny.smolik@state.nm.us	
Date:	Phone: 575-626-0836
	Witness: