

Submit 3 Copies
to Appropriate
District Office
District I
P.O. Box 1880, Hobbs, NM 88240
District II
P.O. Box 1880, Hobbs, NM 88240
District III
P.O. Box 1880, Hobbs, NM 88240

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-88

OIL CONVERSATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 - 021 - 20032
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	L5852
7. Lease Name or Unit agreement Name	WEST BRAVO DOME CDG UNIT
8. Well No.	1
9. Pool name or Wildcat	WEST BRAVO DOME
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4,566

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER CO2 SUPPLY

2. Name of Operator
OXY USA INC.

3. Address of Operator
P.O. Box 50250 Midland, TX 79710

4. Well Location
Unit Letter N : 660 Feet From The SOUTH Line and 1,980 Feet From The WEST Line
Section 11 Township 19 N Range 29 E NMPM HARDING County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: CASING INTEGRITY TEST <input checked="" type="checkbox"/>	

12. Describe Proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.

TD - 2180' PBD - 2180' PERFS - 2032'-2055'

MIRU PU, KILL WELL W/ 2% CLAYBAN WATER. LATCH ONTO TBG & PU DOUGHNUT & UNSCREWED WH WHILE ATTEMPTING TO SET SLIPS ON TBG BELOW WH. CSG STUB WAS CRIMPED. WELD ON NEW BELL NIPPLE & INSTALL NEW WH. RIH W/ TBG, TEST CSG TO 550#, HELD OK, RDPU, SIW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 11 26 91
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

APPROVED BY Ry E Johnson TITLE DISTRICT SUPERVISOR DATE 12-9-91

CONDITIONS OF APPROVAL, IF ANY:

AUTHORIZATION FOR MAINTENANCE IN SHUT-IN OR TEMPORARY ABANDONMENT STATUS EXPIRES _____