

OIL CONSERVATION DIVISION
RECEIVED

'93 JUN 2 AM 8 43

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2033 2716 Field: Bravo Dome

Location: 1979' FNC x 1779' FEL T20N R33E Sec 27 Unit 6

<u>DEPTH</u>	<u>ANGLE INCLINATION DEGREES</u>
<u>244</u>	<u>1°</u>
<u>490</u>	<u>1 1/4</u>
<u>707</u>	<u>1°</u>
<u>1147</u>	<u>1/4</u>
<u>1620</u>	<u>1/2</u>
<u>2091</u>	<u>3/4</u>
<u>2343</u>	<u>1/4</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

John Young
SL. Bty Foreman

B. P. Pedersen
Title: A.P.