

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-152-F Field: Bravo Dome

Location: 2030 FWL X 1959 FNL T2IN. R33E, SEC 15, UNIT F

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>675</u>	<u>3/4</u>
<u>1146</u>	<u>1/2°</u>
<u>1619</u>	<u>3/4°</u>
<u>1904</u>	<u>1°</u>
<u>2345</u>	<u>3/4°</u>
<u>2503</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.



E. J. Ledger
Title: 1-1-1