

(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. 05140-K

Unit _____

APPROVED
APR 2 1963
A. R. BRUNN
ACTING DISTRICT ENGINEER

IN OFFICE 000

UNITED STATES

DEPARTMENT OF THE INTERIOR

PH 1 34 GEOLOGICAL SURVEY

RECEIVED
APR 2 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 15, 1963

Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 33
Wildcat sec. 33 48 6E N.M.P.M.
 (Field) (Twp.) (Range) (Meridian)
Wildcat Socorro New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5693 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth of well is 3037 feet. 10-3/4" casing set and cemented at 238 feet. 5" casing set and cemented at 2710 feet with 275 sacks. Attempted to run tubing to total depth but tubing would not go below a depth of 340 feet. Apparently, well is plugged at this depth. Mudded hole and set a 50-sack plug at 170 to 340 feet, and a 10-sack plug from surface to a depth of 25 feet. Erected regulation marker and cleaned location. Well was plugged and abandoned on April 10, 1963.

RECEIVED
APR 12 1963
U.S. DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. B. Lockhart

Address 1222 West Capitol St.

Little Rock, Arkansas

By J. B. Lockhart

Title _____