1R-711-2726

Plug & Abandon Report

DATE April 7, 2014

From: <u>Lara Weinheimer</u>

To: Lowe, Leonard, EMNRD; VonGonten, Glenn, EMNRD

Cc: "Hack Conder"; "Baker, Larry"; Leking, Geoffrey R, EMNRD; regans@rice-ecs.com

Subject: Plug and Abandon Reports for the Apache Lou Wortham #20 (1R0711-2726) and the Lou Wortham Central

Battery (1R0811-2733)

Date: Monday, April 07, 2014 2:36:09 PM

Attachments: Apache Lou Wortham #20 (1R0711-2726) Plug and Abandon Report of MW-1 and MW-2.pdf

Apache Lou Wortham Central Battery (1R0811-2733) Plug and Abandon Report of MW-1 and MW-2.pdf

Attached you will find the <u>Plug and Abandon Reports of MW-1 and MW-2</u> for Apache's Lou Wortham #20 (1R0711-2726) and Lou Wortham Central Battery (1R0811-2733).

If you have any questions regarding this submission, don't hesitate to contact Hack Conder (1-575-631-6432) or myself at (1-575-441-0431).

Lara Weinheimer

Rice Environmental Consulting & Safety Project Scientist 419 West Cain Hobbs, NM 88240 (575) 441-0431



Rice Environmental Consulting & Safety

P.O. Box 2948, Hobbs, NM 88241 Phone 575.393.2967

April 7th, 2014

Mr. Leonard Lowe

New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87505

> RE: Plug and Abandon Report of MW-1 and MW-2 Apache Corporation Lou Wortham #20 (1R0711-2726): UL/F sec. 11 T22S R37E

Mr. Lowe:

Apache Corporation has retained Rice Environmental Consulting and Safety (RECS) to address potential environmental concerns at the above-referenced site.

On March 5th, 2014, RECS personnel were on site to supervise the plugging and abandonment of MW-1and MW-2 according to the Termination Request submitted to NMOCD on April 19th, 2012 and approved on February 10th, 2014. The wells were plugged with a 1-3% bentonite/concrete slurry and a three foot concrete cap.

Apache acknowledges they have met the requirements in accordance of 19.15.29 NMAC (Part 29; formally Rule 16), and the remediation plan (1R0711-2726) is terminated in accordance with 19.15.29 NMAC and no further action is required.

RECS appreciates the opportunity to work with you on this project. Please call Hack Conder at (575) 393-2967 or me if you have any questions or wish to discuss the site.

Sincerely,

Lara Weinheimer Project Scientist

JC.W.

RECS

(575) 441-0431



Plugging Report

Rice Environmental Consulting and Safety
HCI Drilling
03/05/2014
Apache Lou Wortham #20
MW-1
2"
55'
PVC
Portland/Bentonite Slurry
3'-55'
0'-3'

Copies: Email (RECS) Kenny Cooper



Plugging Report

Client	Rice Environmental Consulting and Safety
Contractor	HCI Drilling
Date Completed	03/05/2014
Site	APACHE LOU WORTHAM #20
Well ID	MW-2
Casing Diameter	4"
Well Depth	85'
Casing Material	PVC
Plugging Material	Portland/Bentonite Slurry
Slurry Interval	3'-85'
Cement Interval	0'-3'

Copies: Email (RECS) Kenny Cooper

Apache Lou Wortham #20 Unit F, Section 11, T-22-S, R-37-E



Removing MW-1, facing southeast

03/05/14



Plugging MW-1 with a 1-3% bentonite/concrete slurry with a 3ft concrete cap, facing northwest 03/05/14





Removing PVC, facing north

03/05/14



MW-1 Plugged, facing north

03/05/14



Removing PVC, facing northeast

03/05/14



Plugging MW-2 with 1-3% Bentonite/concrete slurry with a 3ft concrete cap, facing northeast 03/05/14



MW-2 Plugged, facing northeast

03/05/14