

4RP-4

C-141

OXY CO₂ Plant

06/2014 - future

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED
2014-08-28 P 3:14

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OXY USA Inc.	Contact Eric Maestas
Address 770 Rosebud Rd. Amistad NM 88410	Telephone No. 575-420-7825
Facility Name Bravo Dome Gathering System	Facility Type Carbon Dioxide Gathering System

Surface Owner State	Mineral Owner State	API No. 30-021-20381
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	041	18	32	1700	South	1700	West	Harding

Latitude N 35.81428.33 Longitude W -103.5552833

NATURE OF RELEASE


Type of Release Carbon Dioxide Gas	Volume of Release 1300MCF	Volume Recovered None
Source of Release Pipeline Vent	Date and Hour of Occurrence 8/28/2014 8:30 AM	Date and Hour of Discovery 8/27/2014 10:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Sanchez and Leonard Lowe	
By Whom? Eric Maestas	Date and Hour 8/28/2014 8:08 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Eric Maestas	Approved by Environmental Specialist:	
Title: HES Coordinator	Approval Date:	Expiration Date:
E-mail Address: Eric_Maestas@oxy.com	Conditions of Approval:	
Date: 8/28/2014 Phone: (575)420-7825	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OXY USA Inc.	Contact Eric Maestas
Address P. O. Box 303, Amistad, NM 88410	Telephone No. 575-420-7825
Facility Name Bravo Dome CO2 Gas Unit Collection System	Facility Type CO2 Gas Collection System

Surface Owner Oneal Land and Cattle	Mineral Owner State	Lease No. Bravo Dome CO2 Gas Unit
--	------------------------	--------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22N	34W	1600	South	1700	West	Union

NATURE OF RELEASE

Type of Release CO2 Gas	Volume of Release 800 mcf	Volume Recovered None
Source of Release Bravo Dome CO2 Gas Unit SE Collection System	Date and Hour of Occurrence 8/12/14 - 8:30 am	Date and Hour of Discovery 8/12/14 - 7:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Sanchez	
By Whom? Eric Maestas	Date and Hour 8/12/2014 - 7:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

CO2 gas was vented to replace a 6" block valve on a lateral of the trunk line on Leg 9 of Bravo Dome CO2 Gas Unit Collection System. Wells were shut in, trunk line and lateral block valves were closed to minimize vent, and lines were bled down to atmosphere. There was no produced water lost.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Eric Maestas	Approved by 	District Supervisor:
Title: HES Coordinator	Approval Date: 10/27/14	Expiration Date:
Date: 8/12/14 Phone: 575-420-7825	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OXY USA Inc.	Contact Eric Maestas
Address P. O. Box 303, Amistad, NM 88410	Telephone No. 575-420-7825
Facility Name Bravo Dome CO2 Gas Unit SE Collection System	Facility Type CO2 Gas Collection System

Surface Owner Holland	Mineral Owner Holland	Lease No. Bravo Dome CO2 Gas Unit
--------------------------	--------------------------	--------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22N	34W	1600	South	1700	West	Union

NATURE OF RELEASE


Type of Release CO2 Gas	Volume of Release 800 mcf	Volume Recovered None
Source of Release Bravo Dome CO2 Gas Unit	Date and Hour of Occurrence 06/16/14 - 5:00 PM	Date and Hour of Discovery 06/17/14 - 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Sanchez -	
By Whom? Eric Maestas	Date and Hour 06/17/14 - 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* CO2 gas was vented from a corrosion leak on a 16" steel pipeline of Bravo Dome CO2 Gas Unit Collection System. Wells were shut in, lateral block valve closed to minimize vent, and lines were bled down to atmosphere.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Eric Maestas	Approved by District Supervisor 	
Title: HES Coordinator	Approval Date: 10/27/14	Expiration Date:
Date: 6-17-14	Phone: 575-420-7825	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary