

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Comanche 17 State #1	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-31385
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 17	Township 21S	Range 33E	Feet from the 1880	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.4809442511583 Longitude -103.592500340734

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 35 bbls Oil; 20 bbls PW	Volume Recovered: 0 bbls Oil; 8 bbls PW
Source of Release: Fire	Date and Hour of Occurrence: 1/28/2015 3:00 pm	Date and Hour of Discovery: 1/28/2015 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding – NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 1/30/2015 5:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The oil tank caught fire and the rest of the battery burnt. This is a remote facility and no fire crew responded to the blaze. Upon discovery vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The battery was a total loss. Crews are working to dismantle the debris. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Hydrologist	
Title: Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address: atrujillo@concho.com	Approval Date: 02/13/2015	Expiration Date: 04/13/2015
Date: February 12, 2015	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3534
Phone: 575-748-6940		229137

* Attach Additional Sheets If Necessary

nTO1504426150

pTO1504426337