

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Regency Field Services LLC.	Contact: Crystal Callaway
Address: 421 W. 3 rd Street, Suite 250, Ft. Worth, TX 76102	Telephone No.: 817-302-9407
Facility Name: Carlson 4" (#IRP-1462)	Facility Type: Natural Gas Gathering
Surface Owner: Joyce Marie Willis	Mineral Owner:
	API No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	25S	37E					Lea

Latitude 32.09855 Longitude -103.12644

NATURE OF RELEASE

Type of Release: Crude Oil and Natural Gas	Volume of Release: 80 mcf gas, 20 bbls oil	Volume Recovered: 0 bbls
Source of Release: 4" Natural Gas Pipeline	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 06/15/2007 Time: 8:18 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Tony Savoie, Southern Union Gas Services	Date and Hour: 06/15/2007 08:30 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
By OCD; Dr. Oberding at 9:13 am, Feb 20, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" Natural Gas Pipeline operating at approximately 30 p.s.i. developed a leak releasing approximately 20 bbls of crude oil and approximately 80 mcf of natural gas. The damaged area of pip was excavated and replaced with approximately 200 ft. of 4" poly-pipe. The area affected by the release was pasture land, the area was approximately 3,580 sq.ft. of oil soaked soil and replacement damage. The final remediation will follow the NMOCD guidelines for the remediation of leaks and spills.

Describe Area Affected and Cleanup Action Taken.*

The site was reportedly remediated by Ocotillo Environmental in 2008 and by NOVA Environmental in 2012, impacted material was excavated and transported to the Pitchfork Land farm for proper disposal. Based on the information provided by both Ocotillo and NOVA Environmental, the site has been determined to meet NMOCD regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Crystal Callaway</i>	OIL CONSERVATION DIVISION	
Printed Name: Crystal Callaway	Hydrologist	<i>[Signature]</i> P40
Title: Sr. Remediation Specialist	Approved by Environmental Specialist	
E-mail Address: Crystal.Callaway@regencyllc.com	Approval Date: 02/20/2015	Expiration Date: //
Date: 2/18/15	Conditions of Approval: //	Attached <input type="checkbox"/>
Phone: 817-302-9407		1RP-1462

* Attach Additional Sheets If Necessary