

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Bebidas State #1H	Facility Type: Wellhead	
Surface Owner: State	Mineral Owner:	API No. 30-025-40855

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	16	23S	33E	392'	South	1887'	West	Lea

Latitude 32.2985593051344 Longitude -103.579673759808

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 212 bbls Oil; 225 bbls PW	Volume Recovered: 210 bbls Oil; 220 bbls PW
Source of Release: Wellhead	Date and Hour of Occurrence: 2/14/2015 6:30 am	Date and Hour of Discovery: 2/14/2015 6:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 2/15/2015 10:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED



By OCD; Dr. Oberding at 8:11 am, Mar 02, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when a switch failed at the wellhead. Vacuum trucks were dispatched to recover all standing fluid and dispose of at an NMOCD approved facility. Repairs were made to the wellhead.

Describe Area Affected and Cleanup Action Taken.*
This release impacted the pad primarily and a small area of the pasture. The pad was scrapped and Microblaze was sprayed in the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Hydrologist	
Title: Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address: atrujillo@concho.com	Approval Date: 03/02/2015	Expiration Date: 05/02/2015
Date: February 27, 2015 Phone: 575-748-6940	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3548 217955

* Attach Additional Sheets If Necessary

nTO1506130194

pTO1506130523