

RECEIVED

By OCD; Dr. Oberding at 2:42 pm, Mar 03, 2015

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Daniel Suniga
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5850
Facility Name Mesa Verde 7 Fed 1, 6 Fed 10	Facility Type Oil

Surface Owner Federal Federal	Mineral Owner Federal Federal	API No. 30-025-32398 and 30-025-32751
---	---	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	7	24S	32E	660	North	1980	East	Lea
D	6	24S	32E	430	North	330	West	Lea

Latitude: N 32.261

Longitude: W -103.694

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 20 bbls	Volume Recovered 0 bbls
Source of Release Poly Flow Line	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Thomas Obering OCD	
By Whom? David Simmons	Date and Hour 2/17/2015 @ 10:50 pm and 10:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.***Describe Cause of Problem and Remedial Action Taken.***

A 3" poly line that runs next to the road was damaged when an unknown vehicle struck it resulting in a 20 bbl release of produced water. Power to each one of the water transfer pumps at the Mesa Verde 7 Fed 1 and Mesa Verde 6 Fed 10 was shut off to prevent any more pressure or flow building on the line.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISIONSignature: *Corina Moya*

Printed Name: Corina Moya

Title: Field Admin Support

E-mail Address: corina.moya@dvn.com

Date: 2/19/2015

Phone: 575.746.5559

Approved by *Environmental Specialist*

Approval Date: 03/03/2015

Expiration Date: 05/03/2015

Conditions of Approval:
Site samples required. Delineate and
remediate as per NMOCD guides.

Attached ☐

1RP-3552

6137

* Attach Additional Sheets If Necessary

nTO1506253131

pTO1506253292