

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia	
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455	
Facility Name: EVGSAU #3440-002	Facility Type: Well	
Surface Owner: NMOCD	Mineral Owner:	API No. 30-025-0300800

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	34	17S	35E	1980	North	1980	East	LEA

Latitude 32.7894790923284 Longitude 103.447620650496

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 8.5 BBLs	Volume Recovered: 0 BBLs
Source of Release: Stuffing Box leak	Date and Hour of Occurrence 03/02/2015 1:30 pm	Date and Hour of Discovery 03/02/2015 1:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Jay Garcia	Date and Hour: 03/03/2015 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

ENV- Agency Reportable-2 BO & 6.5 BPW – EVGSAU #3440-002- RR II-MCBU- Buckeye
On Monday March 2nd, 2015 @ 13:30 Hrs. MST, at EVGSAU #3440-002, a flow line leak was found during normal rounds resulting in a release of 2 bbl. of oil and 6.5 bbl. of produced water with none recovered. The affected area will be remediated according to NMOCD and COPC guidelines. This is not a PSE.
Consequence: 1, Likelihood: 5, RR: II

RECEIVED

By OCD; Dr. Oberding at 3:21 pm, Mar 03, 2015

Describe Area Affected and Cleanup Action Taken.*

Release of 6.5 barrels produced water and 2.0 barrels of oil with none recovered. Affected area was 23 foot by 15 foot X 2 inch deep on caliche pad. The affected area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		OIL CONSERVATION DIVISION	
Printed Name: Jay Garcia		Hydrologist	
Title: LEAD HSE		Approved by Environmental Specialist: <i>[Signature]</i> PhD	
E-mail Address: jay.c.garcia@conocophillips.com		Approval Date: 03/03/2015	Expiration Date: 05/03/2015
Date: 01/06/2015		Conditions of Approval: Site samples required. Delineate and remediate areas as per NMOCD guides.	nTO1506255588 Attached <input type="checkbox"/> 1RP-3554

* Attach Additional Sheets If Necessary