<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action								
<b>OPERATOR</b>			al Report		Final Report			
Name of Company: ConocoPhillips Contact: Jay Garcia								
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455							
Facility Name: MCA Battery #02 Facility Type: Well								
Surface Owner: NMOCD Mineral Owner: BLM				API No. 30-025-20522				
LOCATION OF RELEASE								
Unit Letter Section Township Range Feet from the Nort	h/South Line th	South Line Feet from the East/Wes 1325 East			County LEA			
Latitude 32.8129085748644 Longitude 103.775728799082								
NATURE OF RELEASE								
				Recovered. 7 BO				
Source of Release: overfilled tank battery						Iour of Discovery 5 10:00 am		
Was Immediate Notice Given?		If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required		Tomas Oberding- NMOCD Sol Hughes-BLM						
By Whom? Jay Garcia	Date and Hour: 03/04/2015 2:10 pm							
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.								
☐ Yes ⊠ No								
If a Watercourse was Impacted, Describe Fully.*  RECEIVED								
By OCD; Dr. Oberding at 8:33 am, Mar 05, 2015								
Describe Area Affected and Cleanup Action Taken.*								
On 3/3/15, at approximately 8:00 am, a spill occurred at the Buckeye MCA Battery #2. MSO noticed a leak coming from the								
battery. MSO equalized oil to the sales tank to stop the spill. The affected area is 230' X 6' X 1" on caliche pad. Total spill								
volume was 8.3 bbl. of oil and 7 bbl. of oil were recovered by a vacuum truck. A work order will be submitted for the affected area will be remediated according to NMOCD and COPC and BLM guidelines.								
area will be formediated decorating to third obtained and bein galacilities.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger								
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health								
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
. ,	OIL CONSERVATION DIVISION							
Signature: Jay Garcia	The Justice 1							
	Approved by Environmental Specialist:							
Printed Name: Jay Garcia						7 100		
Title: LEAD HSE	Approval Da	te: 03/05/2015	Expiration	Date: 05/0	5/2015			
E-mail Address: <b>jay.c.garcia@conocophillips.com</b>	Conditions o	f Approval:						
,, , , , , , , , , , , , , , , , , , , ,	Site samples required. Delineate and  Attached							
remediate area as per NMOCD								
Date: 01/06/2015 Phone:575-704-2455				1RP-355	6	217817		