

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Federal 27 #1 CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	27	22S	32E					Lea

Latitude N 32.35611° Longitude W 103.66351°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	40 bbls oil	Volume Recovered	35 bbls
Source of Release	Dump valve malfunction on the heater treater caused the tanks to overflow	Date and Hour of Occurrence	04/14/14	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/14/14 @ 3:50 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

By OCD; Dr. Oberding at 8:46 am, Mar 06, 2015

Describe Cause of Problem and Remedial Action Taken.*

A dump valve malfunctioned on the heater treater causing the tanks to overflow and spill 40 bbls of oil onto the ground. A vacuum truck recovered 35 bbls of oil and the dump valve was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 60' on and off location. Remediation was completed according the remediation plan approved by Tomas Oberding of NMOCD via email on 10/15/2014 and approved by Jim Amos of the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.02.27 14:25:31 -06'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 03/06/2015	Expiration Date: //
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: //	Attached <input type="checkbox"/>
Date: 2/27/15	Phone: (575) 628-4121	IRP-3338

* Attach Additional Sheets If Necessary