

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ENERVEST OPERATING	Contact WILLIAM PILKINGTON	
Address 1217 WEST KANSAS	Telephone No. 575-395-3367	
Facility Name B.M. JUSTIS 10	Facility Type GAS WELL	
Surface Owner ENERVEST	Mineral Owner ENERVEST	API No.30025-27630

LOCATION OF RELEASE

Unit Letter E	Section 20	Township 25-S	Range 37-E	Feet from the 1940'	North/South Line NORTH	Feet from the 120'	East/West Line WEST	County LEA
------------------	---------------	------------------	---------------	------------------------	---------------------------	-----------------------	------------------------	---------------

Latitude_32.07052N Longitude_103.11571W

NATURE OF RELEASE

Type of Release CONDENSATE (DRIP GAS)	Volume of Release 10 GALS	Volume Recovered NONE
Source of Release CHANGE BAD VALVE	Date and Hour of Occurrence	Date and Hour of Discovery 3/11/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

By OCD; Dr. Oberding at 10:32 am, Mar 13, 2015

If a Watercourse was Impacted, Describe Fully.*
DEPTH TO GROUND WATER 100'

Describe Cause of Problem and Remedial Action Taken.*
CHANGE OUT BAD VALVE UNDER METER RUN. DUG OUT SOILED AREA TO CLEAN SOIL. HAULED CONTAMINATED SOIL TO SUNDANCE DISPOSAL. HAULED IN FRESH DIRT. REFILLED DUG OUT AREA WITH GOOD CLEAN DIRT

Describe Area Affected and Cleanup Action Taken.*
15' X 15' SOILED
MERRYMAN DUG UP SOILED AREA AND HAULED TO SUNDANCE DISPOSAL. REPLACED CONTAMINATED SOIL WITH CLEAN FRESH SOIL

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: William Pilkington		OIL CONSERVATION DIVISION	
Printed Name: William Pilkington		Approved by Environmental Specialist: [Signature]	
Title: Sr. production Foreman		Approval Date: 03/13/2015	Expiration Date: ///
E-mail Address: wpilkington@enervest.net		Conditions of Approval: ///	Attached <input type="checkbox"/>
Date: 3-13-15	Phone: 575-631-7790 (cell)	1RP-3561	143199

* Attach Additional Sheets If Necessary

nTO1507238089

pTO1507238262