

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact: Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name: NMGSAU 1108	Facility Type: Oil Well

Surface Owner State	Mineral Owner	API No. 30-025-05737
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter G and H	Section 29	Township 19S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N32.632197 Longitude W103.269308

NATURE OF RELEASE

Type of Release: oil and produced water	Volume of Release: 5 barrels of water and 5 barrels of oil	Volume Recovered: 0 barrels
Source of Release: fiberglass line	Date and Hour of Occurrence: 3/9/2015	Date and Hour of Discovery: 3/9/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

By OCD; Dr. Oberding at 3:19 pm, Mar 23, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* 3 inch buried fiberglass flow line ruptured resulting in the loss of fluid. The line was isolated and the area was dusted with caliche.
--

Describe Area Affected and Cleanup Action Taken.* Approximately 6,500 square feet all in pasture. The area was mapped and surface field samples collected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Hydrologist	Approved by Environmental Specialist <i>[Signature]</i> PhD
Title: Environmental Technician	Approval Date: 03/23/2015	Expiration Date: 06/23/2015
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Site samples required. Delineate and remediate are as per NMOCD guides.	Attached <input type="checkbox"/> IRP-3573 873
Date: 3/18/2015 Phone: (432) 631-6982		

* Attach Additional Sheets If Necessary

nTO1508255461

pTO1508255617