

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	MLMU #244	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-11048

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	7	24S	37E	660	South	660	West	Lea County, NM

Latitude N 32.22603° Longitude W 103.20740°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80 bbls	Volume Recovered	10 bbls
Source of Release	Livestock kicked open the valve at the well head	Date and Hour of Occurrence	06/19/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD and Jennifer VanCuren, BLM		
By Whom?	Kathy Purvis	Date and Hour	06/19/2014		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 8:27 am, Mar 24, 2015

Describe Cause of Problem and Remedial Action Taken.*

Livestock kicked open the valve at the well head causing 80 bbls of produced water to spill onto the ground. A vacuum truck recovered 10 bbls of produced water and the valve was closed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 150' x 60' on location near the well head. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email 10/21/2014 and approved by Sol Hughes of the BLM via email on 10/22/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: **Chris Jones**
Digitally signed by Chris Jones
DN: cn=Chris Jones, o, ou,
email=ckjones888@yahoo.com,
c=US
Date: 2015.03.23 10:37:42 -05'00'

Hydrologist

Printed Name: Christopher Jones

Approved by Environmental Specialist: 

Title: HES Specialist

Approval Date: 03/24/2015

Expiration Date: ///

E-mail Address: Christopher.Jones@oxy.com

Conditions of Approval:

Date: 3/23/15

Phone: (575) 628-4121

///

Attached ☐
IRP-3110

* Attach Additional Sheets If Necessary

pTO1417530430