

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Manda B Tract C Tank Battery	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-25438

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	28	22S	37E					Lea County, NM

Latitude N 32.36877° Longitude W 103.16985°

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	Electrical surge cause the tanks to spill over	Date and Hour of Occurrence	06/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking and Tomas Oberding-NMOCD, Jennifer Van Curen-BLM		
By Whom?	Kathy Purvis	Date and Hour	06/23/2014 @ 2:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**  
By OCD; Dr. Oberding at 9:29 am, Mar 24, 2015

Describe Cause of Problem and Remedial Action Taken.\*

An electrical surge caused the tanks to spill 15 bbls of produced water onto the ground. A vacuum truck recovered 5 bbls of produced water and the power was restored.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 8' x 40' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Chris Jones</b> <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.03.23 10:43:19 -05'00'</small>	<b>OIL CONSERVATION DIVISION</b> Hydrologist	
Printed Name: Christopher Jones	Approved by <u>Environmental Specialist</u> <i>[Signature]</i> <b>PhD</b>	
Title: HES Specialist	Approval Date: <b>03/24/2015</b>	Expiration Date: <b>///</b>
E-mail Address: <u>Christopher_Jones@oxy.com</u>	Conditions of Approval: <b>///</b>	Attached <input type="checkbox"/> <b>IRP-3576</b>
Date: <b>3/23/15</b>	Phone: (575) 628-4121	

\* Attach Additional Sheets If Necessary

pTO1508334065