

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: EOG Resources	Contact: Zane Kurtz	
Address: 5909 Champions Drive, Midland, Texas 79706	Telephone No.: (432)686-3667	
Facility Name: Caballo 23 Fed 2H CTB	Facility Type: Well site and separator	
Surface Owner: Bureau of Land Management	Mineral Owner: Bureau of Land Management	API No.: 300254005100

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
	23	25S	33E	150	North	2600	East	Lea

Latitude 32.1229 Longitude -103.5433

NATURE OF RELEASE

Type of Release: Hole on fire tube of separator.	Volume of Release: 20 bbls	Volume Recovered: TBD
Source of Release: Hole on fire tube of separator.	Date and Hour of Occurrence: 3/10/15, Time: Early morning.	Date and Hour of Discovery: 3/10/15, 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 11:37 am, Mar 24, 2015

Describe Cause of Problem and Remedial Action Taken.*

Approximately 20 bbls of oil and produced water released from a hole on the fire tube of the separator. A vacuum truck has been dispatched to the site and will collect as much fluid as possible.

Describe Area Affected and Cleanup Action Taken.*

Soil samples will be collected and the affected area will be assessed. Impacted soil will be excavated and properly disposed of. The excavated area will be backfilled with clean soil and revegetated if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bernard Bockisch</i>	OIL CONSERVATION DIVISION	
Printed Name: BERNARD BOCKISCH	Hydrologist Approved by Environmental Specialist: <i>[Signature]</i>	<i>[Signature]</i> PhD
Title: PROJECT MANAGER	Approval Date: 03/24/2015	Expiration Date: 06/24/2015
E-mail Address: BBOCKISCH@CRA.WORLD.COM	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/>
Date: 3/10/15 Phone: 505-280-0572	1RP-3578	7377

* Attach Additional Sheets If Necessary

nTO1508342153

pTO1508343550