

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jay Garcia
Address: 29 Vacuum Complex Lane	Telephone No. 575-704-2455
Facility Name: MCA 2C header	Facility Type: Well

Surface Owner: NMOCD	Mineral Owner: BLM	API No. 30-025-39356
-----------------------------	---------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	17S	32E	0	South	1830	West	LEA

Latitude 32.810935448197 Longitude 103.730660546581

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 20.5 BO/77.5 BPW	Volume Recovered: 18 BO/67 BPW
Source of Release: Production trunk line.	Date and Hour of Occurrence 03/10/2015 10:15 am	Date and Hour of Discovery 03/10/2015 10:15 am
Was Immediate Notice Given? <div><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required</div>	If YES, To Whom? Tomas Oberding and Sol Hughes	
By Whom? Jay Garcia	Date and Hour: 03/10/2015 3:15 pm	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED

By OGD: Dr. Oberding at 12:17 pm, Mar 24, 2015

RECEIVED


By OCD; Dr. Oberding at 12:17 pm, Mar 24, 2015

Describe Area Affected and Cleanup Action Taken.*

ENV – Agency Reportable – 20.5 BO & 77.5 BPW – MCA 2C Header – RR II – MCBU – Maljamar – On Tuesday March 10, 2015 at 1015 MDT, at the MCA 2C Header, an MSO identified a production trunk line leak resulting in a release of 20.5 bbl. of oil and 77.5 bbl. of produced water. Immediate action was to contact supervision. 18 bbl. of oil and 67 bbl. of produced water were recovered. Location will be remediated according to COPC, NMOCD and BLM guidelines.

Consequence: 2, Likelihood: 3, RR: II

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Jay Garcia</i>		Hydrologist	
Printed Name: Jay Garcia		Approved by Environmental Specialist:	
Title: LEAD HSE		Approval Date: 03/24/2015	
		Expiration Date: 06/24/2015	
E-mail Address: jay.c.garcia@conocophillips.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.		Attached <input type="checkbox"/> IRP-3579

pTO1508344709

Date: 01/06/2015	Phone:575-704-2455	217817
------------------	--------------------	--------

* Attach Additional Sheets If Necessary

nTO1508344498