

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jay Garcia</b>	
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-704-2455</b>	
Facility Name: <b>Vac Abo # 13-10</b>	Facility Type: <b>Well</b>	
Surface Owner: <b>NMOCD</b>	Mineral Owner:	API No. <b>30-025-03070</b>

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	85	18S	35E	1900	South	2310	East	LEA

Latitude 32.4626508,- Longitude 103.298052

### NATURE OF RELEASE

Type of Release: <b>Spill</b>	Volume of Release: 10 BO/14 BPW	Volume Recovered: 5 BO/ 5 BPW
Source of Release: Flow line leak.	Date and Hour of Occurrence 03/10/2015 2:00 pm	Date and Hour of Discovery 03/10/2015 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Tomas Oberding- NMOCD</b>	
By Whom? <b>Jay Garcia</b>	Date and Hour: <b>03/11/2015 11:50 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

**RECEIVED**

By OCD; Dr. Oberding at 12:34 pm, Mar 24, 2015

ENV – Agency Reportable – 10 BO/14 BPW – Vac Abo 14-4 – RR II – MCBU – Buckeye – On Tuesday March 10, 2015 at 1400 MDT, at the Vac Abo 14-4 during normal rounds, the MSO responded to a flow line leak resulting in a release of 10 BO and 14 BPW with 5 BO and 5 BPW recovered. Immediate action was to isolate the well and flow line. The affected area will be remediated according to NMOCD and COPC and guidelines. This is a Tier 3 event. Consequence: 1, Likelihood: 5, RR: II

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jay Garcia		Hydrologist Approved by Environmental Specialist: <i>[Signature]</i> PhD	
Title: LEAD HSE		Approval Date: 03/24/2015	Expiration Date: 06/24/2015
E-mail Address: <b>jay.c.garcia@conocophillips.com</b>		Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	
Date: 01/06/2015 Phone: 575-704-2455		Attached <input type="checkbox"/> 1RP-3580 217817	

\* Attach Additional Sheets If Necessary

nTO1508345662

pTO1508345848