

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Frontier Field Services, LLC	Contact John Prentiss	
Address 65 Mercado Street, Suite 250, Durango, CO 81301	Telephone No. 575-676-3528	
Facility Name Abo Gas Plant	Facility Type Natural Gas Processing Plant	
Surface Owner Frontier Field Services, LLC	Mineral Owner	API No. N/A



LOCATION OF RELEASE

Unit Letter	Section 3	Township 18S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude **32.777768° N** Longitude **-104.250219° W**

NATURE OF RELEASE

Type of Release LOPC of natural gas from 12" buried pressurized pipeline approximately 1/4 mile East of the Abo gas plant. No liquids were released.	Volume of Release Unknown/historic	Volume Recovered: 0 scf
Source of Release Pinhole leak caused from subsurface external force, damage resulting from a rock contacting the pipe.	Date and Hour of Occurrence Unknown/historic	Date and Hour of Discovery 3/19/15 @ 12:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomáš Oberding – NMOCD	
By Whom? Greg Busch – EHS Technician III	Date and Hour 3/19/15 @ 16:12	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A	<div>RECEIVED <i>By OCD; Dr. Oberding at 3:35 pm, Mar 26, 2015</i></div>	
Describe Cause of Problem and Remedial Action Taken.* Wednesday, 3/19/2015: At approximately 12:00, A worker for Chevron spotted an ice-ball on the surface of the high pressure right-of-way coming into the Abo Gas Plant. Frontier was promptly notified and immediately isolated the high pressure line between the Abo Gas Plant and the Coyote compressor station blow down valve. At approximately 16:12 Frontier made prompt notification to NMOCD and BLM Friday, 3/18/2015: Line was de-energized and excavated. A large rock was found resting in contact with the top of the pipe. A 1" diameter hole was discovered after removing the rock suggesting the rock was the cause of the damage. On Saturday, 3/21/2015: At approximately 14:00 pipeline repairs were completed and the pipeline was returned to service.		
Describe Area Affected and Cleanup Action Taken.* No personnel injuries or property damage resulted from this incident. Pressurized line was repaired promptly. Photo documentation attached.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Greg Busch		Approved by Environmental Specialist :  P.D.	
Title: EHS Technician III		Approval Date: 03/26/2015	Expiration Date: ///
E-mail Address: gbusch@akaenergy.com		Conditions of Approval: ///	Attached <input type="checkbox"/> 1RP-3585 221115
Date: 3/26/15 Phone: 970-764-6651			

* Attach Additional Sheets If Necessary

nTO1508556999

pTO1508557188

fTO1508556862

